



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72814
 Promised Date:
 16 JAN 26



WO #: 72814

Customer Name: 60168 - BUFF, AUSTIN Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 2025 CANYON STAR 3947
 Serial#: 163024
 Chassis#: 4UZACMFC7SCVV9661 Date In: 07 JAN 26
 Miles/Hrs: 9543 Time In:
 Tag#: 6745
 Purchased Date:
 Warranty Date:

Job #0 - Warranty

TECH DID NOT GET A PIC

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: LEVELING SYSTEM INOP

CAUSE: LOOSE WIRE AT TOUCH PAD

CORRECTION: REMOVED TOUCHPAD / FOUND WIRE PULLED FROM CONNECTOR. REPAIRED WIRE AND RETESTED.
 .50HRS

Labor

| Job # | Description | Total |
|-------|--------------------------|-------|
| 1 | LEVELING SYSTEM DIAGNOSE | N/C |

Subtotal for Job #1: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer #: 60168
 BUFF, AUSTIN



Customer Signature : _____

Date: 07 Jan 2026

W/O: 72814
Promised Date: 16 JAN 26



Customer #: 60168
BUFF, AUSTIN



Customer Work
Order

