



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72259
Promised Date:
4566002



WO #: 72259

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 26 JAN 26

Invoice#:

Author: BRIAN

Stock Desc: 9604 2026 OPEN RANGE

COLT 26DBS

Serial#: 6X3087

Chassis#: 58TBM0BP5T76X3087

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Date In: 25 AUG 25

Time In:

Job #1 - Internal

CHECK IN NEW UNIT

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

Transferred to RV*72259-1 on 26 JAN 26

Estimate amount was 0.00

Belt rail passenger side above the axle coming loose and has a split will need to be replaced

White in color and 17 feet long

Requesting 5 hours

Will have to remove rear compartment door and frame

Remove j wrap

Remove one side of entry door

Remove rear corner mold and vinyl insert

Remove damaged belt rail

Clean sealant off the unit

Install new belt rail

Install j wrap

Resecure entry door

Reinstall compartment door and frame

Resume corner mold and vinyl insert

Reseal with clear silicone

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Putty clean through out unit , slide room trim and ceiling in slide room , front bedroom batten trim , lower bunk bed wall

CAUSE: Excessive putty and staples sticking up small cut on the wall in lower bunk bed

CORRECTION: Wiped down all excessive putty, set the staples sticking up and puttied the holes

Allied putty to the cut on the wall and wiped down cut is covered up

Work completed

.50 HRS

Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 72259
Promised Date: 15 SEP 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Labor		
Job #	Description	Total
3	TOUCH UP	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: Passenger side compartment door for outdoor kitchen is not square and will not close properly,
Will need to remove all screws inside and get the frame square and resecure the frame so the door will close properly.

CAUSE: MISALIGNED

CORRECTION: WILL NEED TO REMOVE DOOR / RESET AND REINSTALL
.50HRS

Labor		
Job #	Description	Total
4	COMPARTMENT DOOR	N/C
Subtotal for Job #4:		0.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Pdi travel trailer

CORRECTION: Pdi complete

Labor				
Job #	Description			Total
PDI1	PDI TRAVEL TRAILER			N/C
Parts				
Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #PDI1:				0.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize rv basic

CORRECTION: Completed

Labor				
Job #	Description	Total		
WIN-STD	WINTERIZE RV - BASIC	N/C		
Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C
Subtotal for Job #WIN-STD:				0.00



W/O: 72259
Promised Date: 15 SEP 25

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 26 Jan 2026



Customer #: 1000
MYERS "RV" CENTER,
INC.,

