

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2415869
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC7SB940064
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT16BH-50
VANESS ARMIJO-CLEAVER		DEALER RO #	72175
2638 REDONDO SANTA FE NE		CLAIM START DATE	08/27/2025
Rio Rancho, NM 87144		CLAIM END DATE	01/29/2026
USA			
Retail Date of Purchase	07/01/2025	WARRANTY EXPIRATION DATE	07/01/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-197-01-11-001321	Exterior Recept Cover - Including Gasket - Electrical/110 Volt Exterior/Replace/ Electrical		
	Complaint, Cause, Correction			
	Original Note : s.caffrey@myersrv.com, 2025-08-27 10:48:20 :: CUSTOMER STATES RECEPATAACLE LEFT OF ENTRY DOOR LOOSE / Incorrect installation / Removed outlet cover. Removed outlet repositioned wires reinstalled outlet onto base and trim onto outlet. Additional Note : s.caffrey@myersrv.com, 2025-08-27 10:50:35 :: REPAIRED, NOT REPLACED			
Model#		Dlr Sub Hrs	0.10	Sub Labor Amt \$19.00
Serial#		Appr Hrs	0.10	Appr Labor Amt \$19.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	40-196-01-11-001309	Charging Center - USB & 12 Volt - Electrical/12 Volt Interior/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : s.caffrey@myersrv.com, 2025-08-27 10:51:15 :: CUSTOMER STATES BLUETOOTH SPEAKER WILL NOT CHARGE ON THE INSIDE PORT / Component failure / Verified customer concern. Connected Bluetooth speaker to base and speaker would not charge. Checked voltage at wire none present. Removed base from wall and tested for Power. Wires came undone. Had to gain access from pass-through compartment. Loosen axis panel located wire and reinstalled wires. Tested charging base charging base still not producing power. Tested speaker with known good base in pass-through compartment. Speaker is functioning as designed. Recommend replacing interior charging deck for speaker. Part number attached.			
Model#		Dlr Sub Hrs	0.40	Sub Labor Amt \$76.00
Serial#		Appr Hrs	0.40	Appr Labor Amt \$76.00
	Notes			

Part

Line# 1	Item #	Description			
	F100562552	CHARGING DOCK, BLUETOOTH, 2022302425/BTP-185C			
	Model #	Serial #	Part tag		
	Sub Qty	Sub Dlr Price	\$1.92	Sub Freight	\$15.83
	Appr Qty	Appr Dlr Price	\$1.92	Appr Freight	\$15.83
	Notes				

Submitted	Labor Amt	\$95.00	Approved	Labor Amt	\$95.00
-----------	-----------	---------	----------	-----------	---------

Parts & Freight	\$17.75
Total	\$112.75

CUSTOMER SIGNATURE _____ DATE _____

All repairs described have been inspected and are satisfactory.