

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794		CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2531816
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRHB2SB525920
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT190RB
LINDA CECIL		DEALER RO #	72468
2728 DECKER AVE NW		CLAIM START DATE	12/18/2025
Albuquerque, NM 87107		CLAIM END DATE	01/08/2026
USA			
Retail Date of Purchase	10/09/2025	WARRANTY EXPIRATION DATE	10/09/2026

Claim Line Details

Labor

Line# 1	Operation Code 60-136-01-00-001495	Operational Description Water Pump Filter - Plumbing/Fresh Water Supply/Replace/No Tread Code		
	Complaint, Cause, Correction Original Note : stephanie@dealer-advisors.com, 2025-12-18 14:25:23 :: Complaint: Water pressure is weak/no hot water Cause: Water heater would not come on due to flow rate. Removed aerator in bathroom and removed debris, as shown in picture. Water pressure improved slightly, but not enough to turn water heater on and keep it on. Checked kitchen faucet for pressure to ensure that pressure was equal across all fixtures. Eliminated fixture issues. Located water pump and gained access to water pump by removing access cover. Install a known good hose to a jug of water and issue was resolved. Inspection of filter housing and inlet hose showed screen. Housing had a manufacturing defect. The plastic was not all the way removed from the inlet. Correction: Replaced the screen and housing with new. Tested system, no further issues noted. Reassembled all of the disassembled items in reverse order.			
	Model#	Dlr Sub Hrs	0.50	Sub Labor Amt \$95.00
	Serial#	Appr Hrs	0.40	Appr Labor Amt \$76.00
	Notes The time requested is excessive for this repair, time adjusted. NVCB .40 to clean out the water pump filter. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp			

Part

Line# 1	Item #	Description		
	USERPART	10-0698 in line filter		
	Model #	Serial #	Part tag	0000395931
	Sub Qty 1.00	Sub Dlr Price \$12.16	Sub Freight	\$0.00
	Appr Qty 1.00	Appr Dlr Price \$12.16	Appr Freight	\$0.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	60-141-01-00-001583	Interior Shower Head & Hose (Read Notes!!!) - Plumbing/Shower, Tub Surround/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2025-12-18 14:30:01 :: Complaint: Shower head is leaking			
	Cause: Excessive debris throughout orifices, attempted to blow out with air gun, reattached and tested. Still leaking water. Correction: Replace shower head			
Model#		Dlr Sub Hrs	0.10	Sub Labor Amt \$19.00
Serial#		Appr Hrs	0.10	Appr Labor Amt \$19.00
	Notes			

Part					
Line# 1	Item #	Description			
	USERPART	60P15827A shower head			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$6.34	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$6.34	Appr Freight \$0.00

Notes

Labor				
Line# 3	Operation Code	Operational Description		
	30-98-24-00-002295	Bed or Bunk Structure - Interior/Beds, Mattress/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2025-12-18 14:32:57 :: Complaint: Bed base wood grain panel is bowed Cause: The panel was cut too long Correction: Removed both vertical corner trims, removed panel and cut a quarter inch off. Removed all old fasteners from lumber, reattach wood, green panel and corner trim. Filled nail holes and staple holes.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
	Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00

Notes

NVCB .20 to trim down the protruding panel and secure. Per dealers description of this repair.

This authorization is pending ALL requirements of repair code have been met. Dp.

Part					
Line# 1	Item #	Description			
	USERPART	Filler for nail holes			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$1.90	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$1.90	Appr Freight \$0.00

Notes

Submitted	Labor Amt	\$152.00	Approved	Labor Amt	\$133.00
	Parts & Freight	\$20.40		Parts & Freight	\$20.40
	Total	\$172.40		Total	\$153.40

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.