

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0008794	<b>CLAIM STATUS</b>	Paid
<b>MYERS RV CENTER INC</b>		<b>CLAIM</b>	2471248
12024 CENTRAL AVE S.E.		<b>CLAIM ORIGIN</b>	WEB
ALBUQUERQUE, NM 87123		<b>ORIGINAL CLAIM ID</b>	
USA		<b>VIN</b>	5ZT2AVPB7TB940829
		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$190.00	<b>SITE/WAREHOUSE</b>	050 / 050
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	AVT25RBS
RICHARD JARAMILLO		<b>DEALER RO #</b>	72482-1
P.O. BOX 74		<b>CLAIM START DATE</b>	10/17/2025
Peralta, NM 87042		<b>CLAIM END DATE</b>	01/13/2026
USA			
<b>Retail Date of Purchase</b>	07/26/2025	<b>WARRANTY EXPIRATION DATE</b>	07/26/2026

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	70-173-01-11-002093	Furnace Limit Switch - Appliances/Furnace (Dometic, Atwood)/Replace/ Electrical		
	<b>Complaint, Cause, Correction</b>			
	Original Note : ryliefayth@gmail.com, 2025-10-17 11:40:11 :: CUSTOMER STATES FURNACE WILL TURN ON RUNS THRU THE CYCLE BUT WILL NOT IGNITE / After diagnostics, found bad limit switch on furnace at burn chamber. / Pull furnace and replace limit switch 3.0 additional hours needed Additional Note : s.caffrey@myersrv.com, 2025-10-23 12:25:52 :: NEED AUTH TO PULL FURNACE & REPLACE LIMIT SWITCH Additional Note : stephanie@dealer-advisors.com, 2026-01-13 11:13:19 :: Pulled furnace and replace limit switch. Reinstalled furnace. Perform LP drop test. Ran furnace for two hours after repair. Resealed. Work complete.			
	<b>Model#</b> SF-30VHW	<b>Dlr Sub Hrs</b>	4.00	<b>Sub Labor Amt</b> \$760.00
	<b>Serial#</b> 2446009928	<b>Appr Hrs</b>	1.50	<b>Appr Labor Amt</b> \$285.00

### Notes

The vendor will need A picture of the data tag with the model/serial numbers the Dealer to enter the product's model and serial numbers in the appropriate claim fields. and pictures of the complete furnace.  
 All set! Thanks!  
 Has this part already been ordered? Forest River is currently reviewing your request with the vendor. If the vendor does not confirm they are shipping the parts directly to you, you will need to order them through us. To ensure accurate shipping, please verify your address, or we will use the one listed on the claim. Once confirmed, please acknowledge and place the claim back on our side. We'll update the line once we receive the vendor's response. Thank you.  
 Vendor states: Suburban will authorize the replacement of the Limit Switch, field scrap the old part, warranty allowance time is .75 hrs. This authorization is pending ALL requirements of repair code have been met.  
 .75 VCB .75 To Primetime As a goodwill gesture we will cover .75 labor to help dealership out with time changing the limit switch. This authorization is pending ALL requirements of repair code have been met.

### Part

<b>Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	F100813358	LIMIT SWITCH, FOR 2577, SF-30VHQ, 525052			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	<b>Sub Qty</b>	1.00	<b>Sub Dlr Price</b>	\$4.44	<b>Sub Freight</b> \$15.83
	<b>Appr Qty</b>	1.00	<b>Appr Dlr Price</b>	\$4.44	<b>Appr Freight</b> \$15.83

### Notes

<b>Line# 2</b>	<b>Item #</b>	<b>Description</b>
----------------	---------------	--------------------

USERPART  
Model #

Sub Qty 1.00  
Appr Qty 1.00

Sealant  
Serial #

Sub Dlr Price \$14.25  
Appr Dlr Price \$14.25

Part tag

Sub Freight \$0.00  
Appr Freight \$0.00

Notes

---

**Submitted**

Labor Amt \$760.00  
Parts & Freight \$34.52  
Total \$794.52

**Approved**

Labor Amt \$285.00  
Parts & Freight \$34.52  
Total \$319.52

---

**DEALER**

**DATE**

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER**

**DATE**

**SIGNATURE**

All repairs described have been inspected and are satisfactory.