



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71660
 Promised Date:
 20 MAY 26



WO #: 71660
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 03 JAN 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9545 2026 R-POD RP-205
 Serial#: 034604
 Chassis#: 4X4TRPV21TB034604
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 21 MAY 25
 Time In:

Job #1 - Internal

COMPLAINT: CHECK IN NEW UNIT

CAUSE: Complete

CORRECTION: Completed

Labor

| Job # | Description | Total |
|-------|-------------|-------|
| 1 | DIAGNOSIS | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|--------------------------|------|-------|-------|
| SS-I | SHOP SUPPLIES - INTERNAL | 1.00 | N/C | N/C |

Subtotal for Job #1: 0.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: PDI needed

CORRECTION: PDI completed

Labor

| Job # | Description | Total |
|-------|--------------------|-------|
| PDI1 | PDI TRAVEL TRAILER | N/C |

Parts

| Part # | Description | Qty | Price | Total |
|--------|-------------|-------|-------|-------|
| 1000 | L.P. GAS | 10.00 | N/C | N/C |

Other Services

| Code | Description | Qty | Price | Total |
|------|---------------|------|-------|-------|
| SS | SHOP SUPPLIES | 0.00 | N/C | N/C |

Subtotal for Job #PDI1: 0.00

Job #2 - Warranty

COMPLAINT: Cabinet latch are loose in multiple areas.

CAUSE: Cabinetdoor latches are loose in multiple places

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



CORRECTION: Retighten all cabinet latches.

| Labor | | |
|-----------------------------|---------------|-------------|
| Job # | Description | Total |
| 2 | CABINET LATCH | N/C |
| Subtotal for Job #2: | | 0.00 |

Job #3 - Warranty

COMPLAINT: Grey tank sensors not reading full.

CAUSE: Grey tank sensor not reading water level due to wire not stripped behind wall panel.

CORRECTION: Stripped wire for tank tank sensor to make contact reading water level.

| Labor | | |
|-----------------------------|--------------|-------------|
| Job # | Description | Total |
| 3 | GREY SENSORS | N/C |
| Subtotal for Job #3: | | 0.00 |

| | |
|--------------------------|-------------|
| Parts Total: | 0.00 |
| Labour Total: | 0.00 |
| Sublet Total: | 0.00 |
| Extras Total: | 0.00 |
| WORK ORDER TOTAL: | 0.00 |

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 03 Jan 2026

Customer Signature : _____

W/O: 71660
Promised Date: 30 MAY 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,

