



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72271
 Promised Date:
 11 NOV 25



WO #: 72271

Customer Name: 60322 - ARMSTRONG,
 VAL

Completed Date:
 Invoice#:
 Author: SARAH
 Stock Desc: 2024 APEX 265RBSS
 Serial#: 5ZT2CXSBORS047066
 Chassis#:
 Miles/Hrs:
 Tag#: 6855
 Purchased Date:
 Warranty Date:

Date In: 27 AUG 25
 Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES SHOWER LEAKS ON FLOOR WHILE IN USE / WATER DAMAGE ON PANELING AND SLIDE FACIA

CAUSE: Water leak damaged trim and door jam

CORRECTION: Recommend replacement
 Need 1 more batten trim and door jam 4 x78
 2 batten trim pieces are here

Labor

Job #	Description	Total
1	SHOWER LEAK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
FRT	SHIPPING & HANDLING CHARGES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES AWNING MISSING CAPS AND ARM CRACKED

CAUSE: Missing awning front caps

CORRECTION: Attached new awning front caps
 Work completed

Labor

Job #	Description	Total
7	AWNING	N/C

Parts

Part #	Description	Qty	Price	Total
F100358755	AWNING COVER MOTOR SIDE	1.00	N/C	N/C
F100358756	AWNING COVER IDLER SIDE FRONT	1.00	N/C	N/C

Customer #: 60322
 ARMSTRONG, VAL



Subtotal for Job #7: 0.00

W/O: 72271
Promised Date: 11 NOV 25



Job #2 - Warranty

COMPLAINT: BATHROOM SLIDING DOOR LOOSE

CAUSE: Strap broke on bathroom barn door
Taped door open tape pulled paint off the door

CORRECTION: Removed the broken strap removed one screw
New strap with snap was cut to fit and screwed back in place
The tape used to hold door in the open position when removed peeled the paint off the door and door jam
Recommend replacement of the door and door jam or color match the paint and touch up
Hood for approval
Door size 36 x 73
Door jam size 4x 78

Labor

Job #	Description	Total
2	SHOWER DOOR	N/C

Parts

Part #	Description	Qty	Price	Total
04-016553	STRAP - PLASTIC, W/SNAP	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Customer Work Order

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

Customer #: 60322
ARMSTRONG, VAL



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 16 Dec 2025

Customer Signature : _____

