



Warranty Claim Detail

R.O. Number **71814**
Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	0942
Description	Latch-Wesco-Baggage Door Lock
Occurrences	1
Requested Hours	.50
Authorized Hours	.50
Fault Code	29-Miswired
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.00

CUSTOMER COMPLAINT
COMMENT ENTERED ON 11/25/2025 AT 11:47 AM BY DEALER CUSTOMER STATES THE COMPARTMENT DOOR LATCH NEEDS ATTENTION./Misaligned latch and catc h caused damage to latching mechanism on handle.
AUTHORIZATION NOTES
DEALER CORRECTION
COMMENT ENTERED ON 11/25/2025 AT 11:47 AM BY DEALER Replace complete latching mechanism on door. Perform adjustments on both latch and ca tch assemblies.

GENERAL INFORMATION	
Status	Paid
Date In	11/25/2025
Submit Date	11/25/2025
Authorization	No 12/01/2025
Work Complete	Yes 03/16/2026
Payment	Yes 03/25/2026

TOTALS	Requested	Authorized
Labor	92.50	92.50
Sublet	.00	.00
Parts	103.76	103.76
Freight	.00	.00
Adjustments	.00	.00
TOTAL	227.40	227.40
TOTAL PAID		227.40

