



Warranty Claim Detail

R.O. Number 71814
Job 6

COMPLAINT INFORMATION	
Flat Rate Code	0942
Description	Latch-Wesco-Baggage Door Lock
Occurrences	1
Requested Hours	1.00
Authorized Hours	1.00
Fault Code	57-Worn
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:1.00

CUSTOMER COMPLAINT
COMMENT ENTERED ON 01/07/2026 AT 12:39 PM BY DEALER Customer states passenger side 2nd from front compartment door will not open properly , will not operate with remote
AUTHORIZATION NOTES
DEALER CORRECTION
COMMENT ENTERED ON 01/07/2026 AT 12:39 PM BY DEALER Replace complete latching mechanism on the door, perform adjustments on both the latch and the catch assemblies.

GENERAL INFORMATION	
Status	Paid
Date In	06/16/2025
Submit Date	01/07/2026
Authorization	No 01/07/2026
Work Complete	Yes 03/16/2026
Payment	Yes 03/25/2026

TOTALS	Requested	Authorized
Labor	185.00	185.00
Sublet	.00	.00
Parts	207.52	207.52
Freight	38.49	38.49
Adjustments	.00	.00
TOTAL	493.26	493.26
TOTAL PAID		493.26

