



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72567
 Promised Date:
 24 JAN 25



WO #: 72567

Customer Name: 43696 - SAMARITANO, JOSEPH

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 2024 VENTANA 3507
 Serial#: 416428
 Chassis#: 4UZACHFEXRCVG2388
 Miles/Hrs: 1959
 Tag#: 6960
 Purchased Date:
 Warranty Date:

Date In: 20 OCT 25
 Time In:

Job #10 - Warranty

COMPLAINT: CUSTOMER STATES ENGINE ACCESS COVER (INTERIOR) METAL FRAMING DAMAGED

CORRECTION: UNABLE TO REPAIR

Labor

| Job # | Description | Total |
|-------|-------------------------|-------|
| 10 | ENGINE COMPARTMENT SEAL | N/C |

Parts

| Part # | Description | Qty | Price | Total |
|---------|---------------------------------|------|-------|-------|
| 020841D | COVER ENGINE WOOD BOX ONLY | 1.00 | N/C | N/C |
| 163751 | TILE FLOOR SILVER MATTE 12 X 24 | 6.00 | N/C | N/C |

Subtotal for Job #10: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 16 Dec 2025

Customer #: 43696
 SAMARITANO, JOSEPH

