

Warranty Claim Detail

R.O. Number **72790**
 Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	3303
Description	Mirror-Newmar-Paint Complete
Occurrences	1
Requested Hours	2.50
Authorized Hours	2.50
Fault Code	35-Peeling or Flaking
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:2.50

GENERAL INFORMATION	
Status	Pending Claim Submission
Date In	12/29/2025
Submit Date	03/09/2026
Authorization	No 03/10/2026
Work Complete	No
Payment	No

CUSTOMER COMPLAINT
COMMENT ENTERED ON 03/09/2026 AT 02:28 PM BY DEALER Drivers side mirror paint is peeling

AUTHORIZATION NOTES
COMMENT ENTERED ON 03/09/2026 AT 2:53:02 PM BY ALDUNNING PICTURES FROM CASE 01070765

DEALER CORRECTION
COMMENT ENTERED ON 03/09/2026 AT 02:28 PM BY DEALER Defective paint, no impact damage. Paint peeled while on the lot before unit was sold . Strip paint, sand and repaint mirror.

TOTALS	Requested	Authorized
Labor	462.50	462.50
Sublet	.00	.00
Parts	.00	.00
Freight	.00	.00
Adjustments	.00	.00
TOTAL	462.50	462.50
TOTAL PAID		.00

