

Warranty Claim Detail

R.O. Number **72976**
Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	1900
Description	Paint-Newmar-Exterior Side Post Cure
Occurrences	1
Requested Hours	.00
Authorized Hours	.00
Fault Code	45-Scratched
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.00

GENERAL INFORMATION	
Status	Pending Claim Submission
Date In	02/28/2026
Submit Date	03/05/2026
Authorization	No 03/05/2026
Work Complete	No
Payment	No

CUSTOMER COMPLAINT
COMMENT ENTERED ON 03/05/2026 AT 11:40 AM BY DEALER Sublet invoice and pictures emailed. Swirling and cloudy areas of paint down the drivers side.
AUTHORIZATION NOTES
COMMENT ENTERED ON 03/05/2026 AT 11:50:26 AM BY ALDUNNING PICTURES FROM CASE 01069781
DEALER CORRECTION
COMMENT ENTERED ON 03/05/2026 AT 11:40 AM BY DEALER Buff complete driver side of the unit.

TOTALS	Requested	Authorized
Labor	.00	.00
Sublet	400.00	400.00
Parts	.00	.00
Freight	.00	.00
Adjustments	.00	.00
TOTAL	400.00	400.00
TOTAL PAID		.00

