

Warranty Claim Detail

R.O. Number **72976**
Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	1900
Description	Paint-Newmar-Exterior Side Post Cure
Occurrences	1
Requested Hours	.00
Authorized Hours	.00
Fault Code	45-Scratched
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.00

CUSTOMER COMPLAINT
COMMENT ENTERED ON 03/05/2026 AT 11:40 AM BY DEALER Sublet invoice and pictures emailed. Swirling and cloudy areas of paint down the drivers side.
AUTHORIZATION NOTES
COMMENT ENTERED ON 03/05/2026 AT 11:50:26 AM BY ALDUNNING PICTURES FROM CASE 01069781
DEALER CORRECTION
COMMENT ENTERED ON 03/05/2026 AT 11:40 AM BY DEALER Buff complete driver side of the unit.

GENERAL INFORMATION	
Status	Paid
Date In	02/28/2026
Submit Date	03/05/2026
Authorization	No 03/05/2026
Work Complete	Yes 03/06/2026
Payment	Yes 03/10/2026

TOTALS	Requested	Authorized
Labor	.00	.00
Sublet	400.00	400.00
Parts	.00	.00
Freight	.00	.00
Adjustments	.00	.00
TOTAL	400.00	400.00
TOTAL PAID		400.00

