

72976

Estimate No. 1183
Estimate Date: Mar/4/26

Customer: Myers RV Center
12024 Central Ave
Albuquerque NM 87123

Oxidation RV Repair Service
4516 2nd St NW
Albuquerque,NM 87107
505-417-9386
oxidationrv@gmail.com

Make: Grand star Model: New mar
VIN: 4UZAF9FC8TCWM6896
Year 25

Estimate	Amount
Scratches D/side	
Buff Coumpound	
Foam pad	
Hand Glose	
Paid Check: 30948	
Labor	300.00
Parts	
Material ~~Misc.~~	$100.00
Subtotal	
Sales Tax	
Total	400.00

Adjuster Name: _____ Claim Number: _____
Telephone No. _____
Customer Signature: _____ Date: _____