



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72596
Promised Date:
23 JAN 26



WO #: 72596 (Appointment Date: 23 OCT 2025 - Time: 03:15pm)

Customer Name: 42735 - TIDWELL,
DONALD RAY

Completed Date:

Invoice#:

Author: ADVISOR

Stock Desc: 9477 2025 OPEN RANGE

3X 390TBS

Serial#: 58TCM0BV6S3B63147

Chassis#: 58TCM0BV6S3B63147

Miles/Hrs:

Tag#: UNH

Purchased Date: 25 MAR 25

Warranty Date: 25 MAR 25

Date In: 23 OCT 25

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES FLOORING TO THE LEFT OF FRONT ENTRY DOOR IS BUBBLED

CAUSE: Floorbis bubbling near entry door.see pictures

CORRECTION: Lino will have to be peeled back to lay down adhesive and roll bubbles out.

Labor

Job #	Description	Total
1	VINYL FLOORING DIAGNOSE	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES FLOORING BY THE LADDER TO THE BUNK IS BUBBLING

CAUSE: Floor is bubbling near bunk ladder.see pictures

CORRECTION: Lino will have to be peeled back to lay adhesive down and roll bubbles out.

Labor

Job #	Description	Total
2	VINYL FLOORING DIAGNOSE	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES PANTRY HAS COME OFF THE TRACKS

CAUSE: Pantry door rail ball bearing strip has fallen out of track needs to be replaced.

CORRECTION: Remove and replace door rail. Waiting on approval to order part.

Labor

Job #	Description	Total
3	PANTRY DOOR	N/C

Customer #: 42735
TIDWELL, DONALD RAY





Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES MASTER BED IS NOT FOLDING WHEN PULLING SLIDE IN

CAUSE: Bed will extend but no retract due to gear box is damaged.

CORRECTION: Remove and replace retracting arm and gesr box.
 Part on order.

Labor

Job #	Description	Total
4	BED DIAGNOSE	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATED MAIN AWNING HINGE BOLT SNAGGED A WIRE AND PULLED WIRES LOOSE

CUSTOMER STATES THE WHITE PLASTIC WIRE COVER IS ON THE KITCHEN COUNTER NEAR THE SINK

CAUSE: Awning wire was pulled out by arm bolt causing wire cover to come off.

CORRECTION: Inspected wires for damage and reinstalled wire cover with a small bead of clear silicone to hold in place.

Labor

Job #	Description	Total
5	AWNING WIRING DIAGNOSE	N/C

Subtotal for Job #5: 0.00

Job #6 - Internal

COMPLAINT: CUSTOMER STATES SLIDE ON DRIVERS SIDE LOOKS TO HAVE SEAL COMING OUT

CAUSE: Inspected seals on all slideouts.

CORRECTION: All seals are in great conditions.

Labor

Job #	Description	Total
6	SLIDE OUT ROOM DIAGNOSTIC TIME	N/C

Subtotal for Job #6: 0.00

Job #7 - Internal

COMPLAINT: CUSTOMER STATES HOOK UP FOR THE ICE MAKER BLEW - CUST. CONNECTED BUT WOULD LIKE IT CHECKED

CAUSE: Inspected water line around and instide frig.

CORRECTION: Water line is secured wirh tape from customer.

Labor

Job #	Description	Total
7	ICE MAKER COMPRESSOR CONNECTOR REPAIR LEAK	N/C

Subtotal for Job #7: 0.00

Job #8 - Internal

COMPLAINT: CUSTOMER STATES FRONT PASS. JACK HAS PAINT OR SOME KIND OF OVERSPRAY ON IT & WILL NOT GO DOWN WITH OUT HELP



CAUSE: Cycled jack several times without any problems.Checked all wire connections.

CORRECTION: Unable to duplicate problem.

Labor		
Job #	Description	Total
8	JACK	N/C
Subtotal for Job #8:		0.00

Job #NOTE - External

COMPLAINT: CUSTOMER STATES ALL TANKS ARE EMPTY & HE BLEW THE LINES OUT

Labor		
Job #	Description	Total
NOTE	DIAGNOSIS	0.00
Subtotal for Job #NOTE:		0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:

DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 29 Jan 2026

W/O: 72596
Promised Date: 23 JAN 26



Customer #: 42735
TIDWELL, DONALD RAY

