

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2567482
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3CSPB3SG128152
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049B
OWNER INFORMATION		ITEM #	CSF250RLX
DIANA STOW		DEALER RO #	71989-1
503 TRUJILLO ST #A		CLAIM START DATE	02/02/2026
Los Lunas, NM 87031		CLAIM END DATE	02/27/2026
USA			
Retail Date of Purchase	06/28/2025	WARRANTY EXPIRATION DATE	06/28/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	70-164-01-00-001966	Light Lens - Appliances/Range Hood/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-02 10:06:59 :: Complaint: Hood light is inop. Cause: Light is not working. The black wire is not connected inside. Correction: Replace light.			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
	Serial#	Appr Hrs	0.10	Appr Labor Amt\$19.00
	Notes			
	NVCB, Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD			

Part

Line# 1	Item #	Description			
	F100720995	BLACK LIGHT, RANGE HOOD VENTED/VENTLESS, FOR 200-4300, 101004			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$7.59	Sub Freight \$16.26
	Appr Qty	1.00	Appr Dlr Price	\$7.59	Appr Freight \$16.26
Notes					

Submitted	Labor Amt	\$38.00	Approved	Labor Amt	\$19.00
	Parts & Freight	\$23.85		Parts & Freight	\$23.85
	Total	\$61.85		Total	\$42.85

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.