



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73028-1
Promised Date:
10 MAR 26

73028-1

WO #: 73028-1

Customer Name: 61287 - HARRISON,
BERRETT L

Completed Date:
Invoice#:
Author: J.LINDAMAN
Stock Desc: 9638 2026 LACROSSE
3510DB
Serial#: 5ZT2LC0B3TB012590
Chassis#: 5ZT2LC0B3TB012590
Miles/Hrs:
Tag#:
Purchased Date: 07 MAR 26
Warranty Date: 19 MAR 26

Date In: 19 MAR 26
Time In:

Job #1 - Warranty

COMPLAINT: Rear grey tank handle missing

CAUSE: Handle missing

CORRECTION: Replaced handle threaded in place
REQUESTING .10

Labor

Job #	Description	Total
1	GRAY TANK HANDLE	N/C

Parts

Part #	Description	Qty	Price	Total
11-0583	BLADEX METAL HANDLE	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #3 - Warranty

COMPLAINT: Rear Medicine cabinet face fall off

CAUSE: Cabinet face falling off

CORRECTION: Removed whole cabinet from the wall taking out 4 screws
Removed door from cabinet taking out 4 screws
Removed side panel
Took out the screws holding the face in place
Installed new screws slightly longer
Face now secure
Reinstalled cabinet to the wall
Reinstalled the door
REQUESTING .35

Labor

Job #	Description	Total
3	MEDICINE CABINET	N/C

Customer #: 61287
HARRISON, BERRETT L

61287

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Drawer in front bedroom wont close

CAUSE: Drawer wont close

CORRECTION: Cables sticking up behind drawer

Rolled cables up

Drawer closes correctly

REQUESTING .10

Labor

Job #	Description	Total
4	DRAWER	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: Huge gaps between wall and closet floor in front bedroom both closets

CAUSE: Loose panel closet floor

CORRECTION: Found the panel was not attached to the frame near the wall

Was a metal frame used screws to attach the panel

Used white silicone on the under side to seal it

No light coming through

REQUESTING .35

Labor

Job #	Description	Total
5	WALL GAPS	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: Panel under kitchen sink fall off

CAUSE: Panel broke off base plate

CORRECTION: Removed 3 screws

Stapled panel back to base plate

Reinstalled panel

REQUESTING .15

Labor

Job #	Description	Total
6	PANEL	N/C

Subtotal for Job #6: 0.00

Job #8 - Warranty

COMPLAINT: Water heater has a short blowing fuses wont turn on

CAUSE: Water heater blowing fuses on the unit itself

CORRECTION: Began at the water heater replaced the fuse and blew right away

Checked wiring diagram at the water heater showed correct

Went to the back of the water heater showed correct

Went to the controller

Removed controller and tested it found positive wire was on the negative and negative was on positive

Cut the wires and switches the wires reconnected with clamp type wire nuts

Controller came on right away

Started testing of the water heater at the sink next to the controller
Found the sink was plumbed backwards
Tested the whole unit hot water out of all facets
Switched the plumbing on the sink and reinstalled the controller to the wall
REQUESTING 1.5

Labor		
Job #	Description	Total
8	WATER HEATER	N/C

Parts			
Part #	Description	Qty	Price
18638	8 AMP MINI GLASS FUSE	2.00	N/C

Subtotal for Job #8: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 19 Mar 2026

W/O: 73028-1
Promised Date: 19 MAR 26

73028-1

Customer #: 61287
HARRISON, BERRETT L

61287