



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72188
 Promised Date:
 25 AUG 25



WO #: 72188

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9591 2026 R-POD RP-185
 Serial#: 035153
 Chassis#: 4X4TRPU19TB035153
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 11 AUG 25
 Time In:

Job #1 - Internal

Transferred to RV*72188-1 on 21 NOV 25
 Estimate amount was 0.00
 CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C

Other Services

Code	Description	Qty	Price	Total
SS-1	SHOP SUPPLIES - INTERNAL	0.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #PDI1 - Internal

Transferred to RV*72188-1 on 21 NOV 25
 Estimate amount was 0.00
 PRE-PDI NEW TT - 3.0

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #PDI1:				0.00

Job #2 - Warranty

COMPLAINT: Entry door will not close

CAUSE: Installed incorrectly

CORRECTION: Move striker plate a quarter of an inch to allow for proper operation

Labor

Job #	Description	Total
2	ENTRY DOOR ADJUST	19.00

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #2: 19.00

Job #3 - Internal

COMPLAINT: Spare tire holder broken

CAUSE: UNKNOWN

CORRECTION: NEED TO ORDER

Labor

Job #	Description	Total
3	SPARE TIRE HOLDER	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Water leak at rear of unit in underbelly

CAUSE: Incorrect installation

CORRECTION: Had to gain access to black tank flush. Removed rear portion of underbelly from bumper to rear of axle. Removed sewer, spout, Support, propane, lines, and propane quick disconnect. Removed tank flush from tank cleaned both surfaces attempted to use similar product as manufacturer liquid beaultle Decor brand. Product did not hold flood test. Removed tank flush, clean surface and used ABS glue secured tank flesh and flooded system. No leaks noted.

Labor

Job #	Description	Total
4	WATER SYSTEM PUMP DIAGNOSE	1,140.00

Parts

Part #	Description	Qty	Price	Total
06-7828	BUTYL RUBBER SEALANT - 10.1OZ TUBE (GRAY)	1.00	6.33	6.33

Subtotal for Job #4: 1,146.33

Job #5 - Warranty

COMPLAINT: Water pump turns on no pressure

CAUSE: Incorrect installation

CORRECTION: Winterize valave had loose clamps. Installed new clamps and tested. System functioning as designed

Labor

Job #	Description	Total
5	WATER PUMP	38.00

Subtotal for Job #5: 38.00

Job #6 - Warranty

COMPLAINT: Black tank flush vacuum breaker leaking

CAUSE: Loose connection

CORRECTION: Tightened connections and re tested

Labor

Job #	Description	Total
6	BLACK TANK FLUSH	38.00

W/O: 72188
Promised Date: 30 AUG 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,





Subtotal for Job #6: 38.00

Job #7 - Warranty

COMPLAINT: Poor water pressure went on city hook up

CAUSE: Debris in fresh water system.

CORRECTION: Pulled all airator and removed debris. Flushed system until no debris noted.

Labor

Job #	Description	Total
7	CITY WATER PRESSURE	38.00

Parts

Part #	Description	Qty	Price	Total
38-8522	TEFLON THREAD SEAL	1.00	0.40	0.40

Subtotal for Job #7: 38.40

Job #8 - Warranty

COMPLAINT: Door side rear stabilizer jack bent

CAUSE: UNKNOWN

CORRECTION: Not on DAF . Need to order

Labor

Job #	Description	Total
8	STABILIZER	1.90

Subtotal for Job #8: 1.90

Job #9 - Warranty

SPARE TIRE CARRIER U-BOLT IS BROKEN

Subtotal for Job #9: 0.00

Job #10 - Warranty

FRONT SHADE LOWER BRACKET IS BROKEN

Subtotal for Job #10: 0.00

Job #11 - Warranty

L/S COMPARTMENT PANEL IS UNATTACHED

Subtotal for Job #11: 0.00

Parts Total: 6.73
 Labour Total: 1,274.90
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 1,281.63



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Dec 2025

Customer Signature : _____

Customer Work Order

W/O: 72188
Promised Date: 30 AUG 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,

