



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72876
Promised Date:
29 JAN 26



WO #: 72876 (Appointment Date: 29 JAN 2026 - Time: 08:15am)
Customer Name: 61021 - PEACOCK, VELORA
Completed Date: 27 FEB 26
Invoice#: 308832
Author: BRIAN
Stock Desc: 2025 NO BO 18.2
Serial#: 5NHTRDT18TD211522
Chassis#: Date In: 29 JAN 26
Miles/Hrs: Time In:
Tag#: 7055NK
Purchased Date:
Warranty Date:

Job #0 - Warranty

CLAIM: 2565626

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES FURNACE WILL TURN ON BLOWS, BUT NO WARM AIR

CAUSE: Furnace would run with a flame and shut off then turn back on not run long enough to warm the unit

CORRECTION: Plugged the unit into shore power
Checked to make sure the gas was on
Turned the furnace on watch through the peep hole and could see a flame
After several minutes the flame began turning on and off . Would run come for 15 to 30 seconds and turn off
Tested the operating pressure and found it to be 10.5 adjusted it to 11
Disconnected the furnace including the gas line thermostat wires and power wires
Removed the screws and pulled the exhaust out.
Took the furnace in the shop
Tested circuit board and found it was working correctly
Bench tested the furnace and found it was operating correctly
Reinstalled the furnace connected the gas thermostat and power
Turned the furnace on and was operating the same way.
Disconnected the thermostat and power
Used a outside power source and the furnace operated correctly with house propane
Connected the house power and tested the furnace again and was operating correctly
Connected the thermostat and the furnace began turning on and off as it was doing before
Connected an analog thermostat and the furnace was working properly
Found the thermostat was not working properly and recommend replacement
The analog thermostat was left connected the customer lives in the unit
On hold for parts
Removed temp thermostat
Installed new thermostat
Tested the air conditioner
Tested the heater
Both work correctly
Work completed

Customer #: 61021
PEACOCK, VELORA





Labor		
Job #	Description	Total
1	FURNACE DIAGNOSE	760.00

Parts				
Part #	Description	Qty	Price	Total
1701	ATC-7.5 FUSE	1.00	0.75	0.75
F100211027	A/C, DIGITAL HEAT/COOL THERMOSTAT - BLACK - DUCTED UNITS ONLY	1.00	33.45	33.45

Other Services				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	16.30	16.30

Subtotal for Job #1: 810.50

Job #2 - External

COMPLAINT: CUSTOMER STATES INVERTER NOT WORKING

CAUSE: Customer complaint inverter not working

CORRECTION: Found the gfi breaker was tripped
 Turned breaker on
 Disconnected shore power tested all plugs and all had power
 Checked the inverter and all readings were correct

Labor		
Job #	Description	Total
2	INVERTER DIAGNOSE	N/C

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: INSTALL MANUAL T-STAT

CAUSE: Unit has bad thermostat

CORRECTION: Installed a manual thermostat so the customer could have heat until the replacement arrives
 Tested the furnace works correctly

Labor		
Job #	Description	Total
3	T-STAT	N/C

Parts				
Part #	Description	Qty	Price	Total
41-1068	WALL THERMOSTAT WHT	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 34.20
 Labour Total: 760.00
 Sublet Total: 0.00
 Extras Total: 16.30
WORK ORDER TOTAL: 810.50



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC .

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 28 Feb 2026

Customer Signature : _____

Customer Work Order

W/O: 72876
Promised Date: 29 JAN 26



Customer #: 61021
PEACOCK, VELORA

