

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2610377
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	4X4TUMA23TB035532
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	080 / 080B
OWNER INFORMATION		ITEM #	UMT25RL-80
		DEALER RO #	73034
		CLAIM START DATE	03/16/2026
		CLAIM END DATE	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-101-24-00-001074	Interior Door Jamb, U-Channel, Casing, Frame - Interior/Interior Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-03-16 12:21:44 :: Complaint: Pocket door is not functioning			
	Cause: There is a brace on the inside of the wall for the pocket door. The staples did not hold and the wood popped out enough to make contact with the door when it is fully closed. Correction: Remove the upper header board, unclipped the door and removed the door from the track. Unsecured the piece of wood. Can hold piece of wood up against the wood panel and staple the wood panel being the toilet to resecure the board inside the wall			
	Fill all holes with putty and stain to match. Rehang the door and reinstall the header board.			
Model#	Dlr Sub Hrs	0.85	Sub Labor Amt	\$161.50
Serial#	Appr Hrs	0.85	Appr Labor Amt	\$161.50
	Notes			
	changed to more suitable code			
	Authorized to repair as stated.			

Submitted	Labor Amt	\$161.50	Approved	Labor Amt	\$161.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$161.50		Total	\$161.50

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.