



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25206



WO #: 25206

Customer: 55896 - PRINCE, ROXANNE  
 Address: 2262 MURPHYS CHAPEL DR  
 SEVIERVILLE, TN  
 37876

Home Phone: 231-878-0198

Work Phone:  
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11067  
 Stock Desc: 2025 FW FOREST RIVER  
 SANDPIPER 3370RLS  
 Model: 3370RLS  
 Serial #: 4X4FSAK25SJ047878  
 Chassis #:  
 Mileage:  
 Key #: 8500  
 Req'n #:  
 License #:  
 Trim:

Purchase Date: 26 MAR 25  
 Date In: 01 APR 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed:  
 Warr. Date: 26 MAR 25

**Job #1 - Warranty**

COMPLAINT: BOTTOM DRAWER AT THE ENTRY INTO KITCHEN GUIDE BROKE AND THE DRAWER WILL NOT WORK

CAUSE: DRAWER GUIDE BROKE

CORRECTION: REPLACE DRAWER GUIDE  
 LABOR .20

**Labor**

| Job # | Description       | Hours | Total |
|-------|-------------------|-------|-------|
| 1     | R&R DRAWER GUIDES | 0.20  | 33.00 |

**Parts**

| Part #     | Description                    | Qty  | Price | Total |
|------------|--------------------------------|------|-------|-------|
| F100609868 | DRAWER GUIDE 12"; DRAWER SIDE  | 2.00 | 0.88  | 1.76  |
| F100609867 | DRAWER GUIDE 12"; CABINET SIDE | 2.00 | 2.70  | 5.40  |

**Subtotal for Job #1: 40.16**

**Job #2 - Warranty**

COMPLAINT: BOTTOM DRAWER ON KITCHEN ISLAND WILL NOT CLOSE ALL THE WAY

CAUSE: DRAWER GUIDE IS NOT GRABBING ON THE LEFT SIDE, FAULTY GUIDE.

CORRECTION: REPLACE DRAWER GUIDE  
 LABOR .20

**Labor**

| Job # | Description       | Hours | Total |
|-------|-------------------|-------|-------|
| 2     | R&R DRAWER GUIDES | 0.20  | 33.00 |

**Parts**

| Part #     | Description                    | Qty  | Price | Total |
|------------|--------------------------------|------|-------|-------|
| F100610150 | DRAWER GUIDE 16"; DRAWER SIDE  | 2.00 | 1.05  | 2.10  |
| F100609869 | DRAWER GUIDE 16"; CABINET SIDE | 2.00 | 3.24  | 6.48  |

**Other Services**

| Code | Description          | Qty  | Price | Total |
|------|----------------------|------|-------|-------|
| SHP  | SHIPPING/FREIGHT FEE | 1.00 | 38.59 | 38.59 |

**Subtotal for Job #2: 80.17**

Customer #: 55896  
 PRINCE, ROXANNE



**Job #3 - Warranty**

COMPLAINT: COMPARTMENT DOOR TO THE RIGHT OF THE ENTRY DOOR IS NOT CLOSING ALL THE WAY ON THE LEFT SIDE.

CAUSE: COMPARTMENT DOOR NEEDS TO BE ADJUSTED TO CLOSE SEAL CORRECTLY

CORRECTION: ADJUST COMPARTMENT DOOR

LABOR .20

**Labor**

| Job #                       | Description               | Hours | Total        |
|-----------------------------|---------------------------|-------|--------------|
| 3                           | ADJUSTED COMPARTMENT DOOR | 0.20  | 33.00        |
| <b>Subtotal for Job #3:</b> |                           |       | <b>33.00</b> |

**Job #4 - Warranty**

COMPLAINT: COMPARTMENT DOOR AT THE FRONT OF THE UNIT WILL NOT CLOSE ALL THE WAY

CAUSE: COMPARTMENT DOOR IS OUT OF ADJUSTMENT NOT CLOSING CORRECTLY

CORRECTION: ADJUST ENTRY DOOR

labor .20

**Labor**

| Job #                       | Description | Hours | Total        |
|-----------------------------|-------------|-------|--------------|
| 4                           | ADJUSTED    | 0.20  | 33.00        |
| <b>Subtotal for Job #4:</b> |             |       | <b>33.00</b> |

|                          |               |
|--------------------------|---------------|
| Parts Total:             | 15.74         |
| Labour Total:            | 132.00        |
| Sublet Total:            | 0.00          |
| Extras Total:            | 38.59         |
| <b>WORK ORDER TOTAL:</b> | <b>186.33</b> |



Customer #: 55896  
PRINCE, ROXANNE

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X \_\_\_\_\_

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 14 Apr 2025

