



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25284
Promised Date:
47 ADD 25



Customer #: 75346
LAMB, CENIA



WO #: 25284 (Appointment Date: 16 APR 2025 - Time: 10:00am)

Customer: 75346 - LAMB, CENIA
Address: 635 CHESTNUT GROVE RD
DANDRIGE, TN
37725

Home Phone: 423-200-6654

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 10825

Stock Desc: (10825) 2024 KZ-RV SPORTSMEN SE

261BHKSE

Model: 261BHKSE

Serial #: 4EZTU2824R5060526

Chassis #:

Mileage: 0

Key #: 2000

Req'n #:

License #:

Trim:

Purchase Date: 28 MAY 24

Date In: 15 APR 25

Promise Date: 17 APR 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 28 MAY 24

Job #1 - External

DEWINTERIZE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: VINYL INSERT CRACKING ON FRONT OF THE UNIT.

CAUSE: VINYL INSERT HAS CRACKED AND COMING OFF THE FRONT OF THE UNIT

CORRECTION: REMOVE AND REPLACE THE VINYL INSERT ON FRONT OF THE UNIT.
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE OUTSIDE SHOWER HOSE AND HEAD IS DAMAGED AND THE DOOR WILL NOT STAY LATCHED.

CAUSE: LATCH FAILED WHILE TRAVELING AND THE SHOWER HOSE AND HEAD WAS DRAGGING ON THE GROUND.

CORRECTION: R&R EXT SHOWER DOOR LATCH AND SHOWER HOSE AND HEAD.
LABOR .30

Subtotal for Job #3: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 17 Apr 2025

Customer Work
Order

W/O: 25284
Promised Date: 17 APR 25



Customer #: 75346
LAMB, CENIA

