



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25293



WO #: 25293

Customer: 92474 - SMITH, LISA
Address: 522 3RD ST
NEWPORT, TN
37821

Home Phone: (615) 939-7002

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11036

Stock Desc: 2025 FW FOREST RIVER

SANDPIPER 3800RK

Model: 3800RK

Serial #: 4X4FSAP22SJ047717

Chassis #:

Mileage:

Key #: 8500

Req'n #:

License #:

Trim:

Purchase Date: 31 JAN 25

Date In: 16 APR 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 17 APR 25

Warr. Date: 31 JAN 25

Job #1 - Warranty

COMPLAINT: KING WIFI RANGER NOT SECURED TO WALL

CAUSE: SCREWS HAVE WORKED LOOSE FROM INSTALL AND NOT HOLDING PLATE ON WALL.
THIS WAS NOTED ON DAF.

CORRECTION: RESECURE PANEL TO WALL.

LABOR .10

Labor

Job #	Description	Hours	Total
1	RESECURED PANEL	0.10	16.50
Subtotal for Job #1:			16.50

Job #2 - Warranty

COMPLAINT: SLIDE OUT FASCIA HAS SEVERAL NAIL/STAPLE HOLES FROM BUILD.

CAUSE: HOLES WERE NOT FILLED AFTER INSTALL, NOTED ON DAF

CORRECTION: FILL, COLOR AND CLEAN AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	FILL, COLOR AND CLEAN AREA	0.30	49.50
Subtotal for Job #2:			49.50

Parts Total: 0.00

Labour Total: 66.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 66.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 92474
SMITH, LISA



Customer Signature : _____

Date: 17 Apr 2025

W/O: 25293



Customer #: 92474
SMITH, LISA



Customer Work
Order

