

KZRV, LP APPOINTMENT DATE VEHICLE ARRIVED WSO DATE PRE
Sportsmen - New Vision 4/22/2025

REPAIR COMPLETION DATE CUSTOMER NOTIFIED VEHICLE PICK
...

RV SERIAL # MAKE MODEL
4EZTL3321S403557 Lookup CONNECT C312RE
DEALER ... CUSTOMER ...

DEALER # DEALER NAME CONTACT DENIA
TRI030 Tri-Am RV Center of E. Tn, Inc Dealer Stock
LABOR RATE FEE RATE ADDRESS TELEPHONE
175.00 15.00
ADDRESS TELEPHONE CITY STATE ZIP EQUIP
1202 Idell Road
CITY STATE ZIP EQUIP
Bulls Gap TN 37711

JOB OPERATION 1 CAUSE OPER
Noted on DAF 440
Ceiling light in light area on floor and cover will not stay on
REMEDY HOUR
R&R ceiling light and test 0.20
INITIALS SUPPL
LABC
PART

PART # PART # PART DESCRIPTION PART DESCRIPTION # QTY UNIT RETURN TAG # TO
\$ PAF

Delete SUB-1
JOB OPERATION 2 CAUSE OPER
Noted on DAF, shade is faulty 660
Shade to left of the seating (DS) will not retract up and tech is not able to adjust
REMEDY HOUR
R&R shade and test 0.10
INITIALS SUPPL
LABC
PART

PART # PART # PART DESCRIPTION PART DESCRIPTION # QTY UNIT RETURN TAG # TO
\$ PAF

Delete SUB-1
JOB OPERATION 3 CAUSE OPER

Submit | UPS Label

Add Job Operation | Ter