

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0049080	CLAIM STATUS	Paid
TRI AM RV CENTER OF EAST TN		CLAIM	2318906
1202 IDELL ROAD (I-81 EXIT 23)		CLAIM ORIGIN	WEB
BULLS GAP, TN 37711		ORIGINAL CLAIM ID	
USA		VIN	4X4TRLA27RD456310
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	010 / 010B
OWNER INFORMATION		ITEM #	RLT2511S
MICHAEL WHITE		DEALER RO #	25337
2474 MUDDY HALLOW RD		CLAIM START DATE	06/02/2025
Dandridge, TN 37725		CLAIM END DATE	06/03/2025
USA			
Retail Date of Purchase	12/22/2023	WARRANTY EXPIRATION DATE	12/22/2024

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	SB-387-09-00-004564	51-1798 - MAGIC CHEF REFRIGERATOR VENTS NOT CUT OUT - INSPECTION AND PERFORM REMEDY - Technical Service Bulletin/Refrigerator/Perform/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-06-02 12:22:55 :: Complaint: Customer said they have a fridge recall vent not cut large enough Cause: Found the vent was not cut correctly and recall needs to be done			
	Correction: Cut vent to MFG spec recall complete			
Model#	Dlr Sub Hrs	0.35	Sub Labor Amt	\$57.75
Serial#	Appr Hrs	0.35	Appr Labor Amt	\$57.75
	Notes			
	Hello, the allowed labor is .35 but i see only .10 was requested, can you advise. kerb			
	That was requested by mistake, please reset to adjust			
	Requested time adjusted. Thank you!			
	bvidllon			

Submitted	Labor Amt	\$57.75	Approved	Labor Amt	\$57.75
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$57.75		Total	\$57.75

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.