

Pre-Authorization

Pre-Authorization number PA03845257		Reference no: 25341	Status: Approved	Approved by anglr	Approved date 4/30/2025
Servicing Dealer	Name	Address	VIN	Retail sold on	

8140	Tri-AM RV Center of East TN	Tri-AM RV Center of East TN 1202 Idell Rd Bulls Gap, TN 37711	4YDFAAP2XSZ915437	4/12/2025
------	-----------------------------	---	-------------------	-----------

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6109314B	Holding Tank Flus	0.00	1.00	0.30		1	0.20	Complaint:The black tank flush is not allowing water to make it to the tank. Water is not leaking, but can hear a buzzing noise under the bathroom sink Cause:Due to manufacturer defect, black tank flush connection was not allowing water to pass through Correction:R&R the black flush connection KRV – Labor time approved in accordance with Keystone RV's flat rate manual. VCB: Vendor Charge Back item. (This is a Keystone RV internal notation only)
2	6109414A	Holding Tank Flus	0.00	0.30	0.20		1	0.20	Complaint:Leak at black tank vacuum breaker Cause:Manufacturer had not installed a washer during install Correction:Installed washer, tested and vacuum breaker no longer leaking KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual
Pre-Authorization number PA03845257					0.50				

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company