



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25342
Promised Date:
26 APR 25



Customer #: 90088
JACKSON, DUSTIN



WO #: 25342 (Appointment Date: 28 APR 2025 - Time: 09:00am)

Customer: 90088 - JACKSON, DUSTIN
Address: 6926 SIMS RD
HARRISON, TN
37341

Home Phone: (423) 582-7113

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10799

Stock Desc: 2023 TT KZ-RV CONNECT 282FKK

Model: 282FKK

Serial #: 4EZTL2920P7050675

Chassis #:

Mileage:0

Key #: 2500

Req'n #:

License #:

Trim:

Purchase Date: 24 JUN 23

Date In: 26 APR 25

Promise Date: 26 APR 25

Promise Time: 09:00am

Schedule Date:

Completed: 30 MAY 25

Warr. Date: 24 JUN 23

Job #1 - Warranty

COMPLAINT: cs that the electric side of the water heater is inop

CAUSE: TESTED AND FOUND OPEN LOOP ON HEATING ELEMENT

CORRECTION: REMOVE AND REPLACE THE HEATING ELEMENT THEN TEST.

LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED ELEMENT	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
504189	WATER HEATER,ELEMENT,ELECTRIC,120 VOLT,SUBURBAN	1.00	18.03	18.03

Subtotal for Job #1: 105.53

Job #2 - Warranty

COMPLAINT: CS THAT THE MOLDING BY THE ENTRY DOOR HAS COME LOOSE LEFT HAND SIDE WHEN WALKING IN

CAUSE: IMPROPER INSTALLATION, TRIM IS TO LONG.

CORRECTION: REMOVE TRIM, CUT TO FIT AND RESECURE IN PLACE.

LABOR .10

Labor

Job #	Description	Hours	Total
2	RESECURED IN PLACE	0.10	17.50

Subtotal for Job #2: 17.50

Job #3 - Warranty

CS THAT THE SHOWER DOOR HAS COME LOOSE CHECK AND ADVISE BOTTOM TRACK

Subtotal for Job #3: 0.00

Job #4 - Warranty

CS WE ORDERED A CABINET FOR THIS UNIT FROM AN OLD WO CABINET DOOR IS BY THE BATHROOM





Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: CS THAT THE FAUCET IN THE KITCHEN IS LEAKING AT THE BASE

CAUSE: WATER IS COMING FROM THE BASE OF THE FAUCET, INTERNAL FAILURE.

CORRECTION: REMOVE, REPLACE AND TEST FAUCET.

LABOR .50

Labor

Job #	Description	Hours	Total
5	REPLACED FAUCET	0.40	70.00

Parts

Part #	Description	Qty	Price	Total
153943	FAUCET, KITCHEN, BLK MATTE	1.00	86.64	86.64

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #5: 156.64

Job #6 - Warranty

COMPLAINT: CS THAT THE SHADE OVER THE DINETTE LOWER BOTTOM CORNER HAS COME LOOSE

CAUSE: SCREW PULLED AWAY FROM WALL.

CORRECTION: FILL HOLE, OVERLAY AND MOVE SCREW TO CORRECT PLACE TO HOLD THE SHADE IN PLACE.

LABOR .30

Labor

Job #	Description	Hours	Total
6	MISC. LABOR CODE	0.10	17.50

Parts

Part #	Description	Qty	Price	Total
161922	TAPE,SEAM,HIGHLAND COVE EMPRESS,1"X150'	2.00	0.24	0.48

Subtotal for Job #6: 17.98

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING_____

CHECK SKYLIGHTS_____

CHECK ROOF VENTS_____

CHECK LUBE & ANTENNA_____

CHECK SATELLITE_____

CHECK RUBBER_____

Subtotal for Job #ROOFINS: 0.00

Job #7 - External

CHECK SLIDE SEALS





Subtotal for Job #7: 0.00

Job #8 - Warranty

COMPLAINT: CS THAT THE LED DOCKING LIGHT ON THE JACK WILL NOT WORK.

CAUSE: TECH DETERMINED LIGHT IS GETTING POWER BUT WILL NOT WORK.

CORRECTION: REMOVE, REPLACE JACK AND TEST.

LABOR 1.0

Labor

Job #	Description	Hours	Total
8	REPLACED JACK	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
164579	JACK,TONGUE,ELECTRIC	1.00	156.38	156.38

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	28.20	28.20

Subtotal for Job #8: 237.08

Job #9 - Warranty

COMPLAINT: CS THAT THE RIGHT REAR TAIL LIGHT IS GETTING A FAULT IN THE TRUCK WHEN PLUGGED IN

CAUSE: TECH DETERMINED THE LIGHT IS FAULTY AND NOT WORKING.

CORRECTION: REPLACE THE REAR TAIL LIGHT.

LABOR .30

Labor

Job #	Description	Hours	Total
9	REPLACED	0.20	35.00

Parts

Part #	Description	Qty	Price	Total
142170	LIGHT,TAIL,LED,W/O LICENSE LIGHT,SURFACE MOUNT,ELLIPTICAL,CLEAR BASE	1.00	19.81	19.81

Subtotal for Job #9: 54.81

Job #WASH - External

WASH UNIT

Subtotal for Job #WASH: 0.00

Parts Total: 281.34
 Labour Total: 280.00
 Sublet Total: 0.00
 Extras Total: 28.20
WORK ORDER TOTAL: 589.54

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
 X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967



Customer Signature : _____

Date: 30 May 2025

W/O: 25342
Promised Date: 26 APR 25



Customer #: 90088
JACKSON, DUSTIN



Customer Work
Order

