



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 25400



WO #: 25400

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:  
Author: S.DAVIS  
Location: IH  
Invoice #:

Stock #: 11105  
Stock Desc: 2025 TT FOREST RIVER  
ROCKWOOD SIGN 8263MBR  
Model: 8263MBR  
Serial #: 4X4TRLF24S1908844  
Chassis #:  
Mileage: 0  
Key #:  
Req'n #:  
License #:  
Trim:

Purchase Date:  
Date In: 05 MAY 25  
Promise Date:  
Promise Time:  
Schedule Date:  
Completed:  
Warr. Date:

**Job #1 - Warranty**

COMPLAINT: SHOWER SURROUND HAS A GAP ON THE RIGHT SIDE.

CAUSE: NOTED ON DAF  
THE INTERIOR WALL THAT THE SURROUND IS ON HAS A WAVE IN IT. THIS IS CAUSING THE  
SURROUND TO HAVE THE GAP.

CORRECTION: REMOVE ALL CORNER TRIM TO ACCESS THE WALL PANEL, A BRACE NEEDS TO BE  
ADDED BEHIND THE WALL PANEL SO THE SURROUND WILL FIT CORRECTLY.  
LABOR 2.0

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: VALANCE AT THE TOP OF THE BATHROOM DOOR OVERLAY IS TORN AND WALL HAS  
FILLER ON IT.

CAUSE: NOTED ON DAF

CORRECTION: VALANCE OVERLAY NEEDS TRIMMED DOWN, AREA NEEDS TO BE CLEANED.  
LABOR .20

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: BATHROOM CABINET DOOR IS LOOSE AT THE BOTTOM.

CAUSE: SCREW HOLE IS STRIPPED WHERE THE HINGE IS, NOTED ON DAF.

CORRECTION: REMOVE THE HINGE, FILL HOLE AND REINSTALL HINGE.  
LABOR .30

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: CORNER TRIM AT THE BOTTOM IN THE KITCHEN IS DAMAGED AND HAS BLACK  
MARKS ON THE BOTTOM.

CAUSE: NOTED ON DAF.

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



CORRECTION: REMOVE AND REINSTALL NEW TRIM.  
LABOR .20

**Subtotal for Job #4: 0.00**

**Job #5 - Warranty**

COMPLAINT: FASCIA ON LEFT OF THE LIVING SLIDE IS CROOKED AND STICKS OUT.

CAUSE: NOTED ON DAF.  
FASCIA WAS INSTALLED SIDEWAYS

CORRECTION: FILL GAP, COLOR AND BLEND AREA.  
LABOR .10

**Subtotal for Job #5: 0.00**

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_  
-----

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 05 May 2025

Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

W/O: 25400

