



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25408



WO #: 25408

Customer: 76295 - HAEHNER, CARL  
 Address: 154 MANOR LN  
 JONESBOROUGH, TN  
 37659

Home Phone: (423) 328-8595

Work Phone:  
 Author: S.DAVIS  
 Location: IH  
 Invoice #:

Stock #: 11096  
 Stock Desc: 2025 TT FOREST RIVER  
 ROCKWOOD ULTRA 2606WS  
 Model: 2606WS  
 Serial #: 4X4TRLB20SZ197313  
 Chassis #:  
 Mileage:  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date: 19 APR 25  
 Date In: 07 MAY 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed: 14 MAY 25  
 Warr. Date: 19 APR 25

**Job #1 - Warranty**

COMPLAINT: INTERIOR FASCIA ON SLIDE OUT HAS NAIL/.STAPLE HOLES ON THE SQUARES.

CAUSE: HOLES ARE FROM THE INSTALL AT FACTORY.

CORRECTION: FILL, COLOR AND BLEND THE AREA.

LABOR .30

**Labor**

Job #	Description	Hours	Total
1	REPAIR	0.30	49.50
<b>Subtotal for Job #1:</b>			<b>49.50</b>

**Job #2 - Warranty**

COMPLAINT: INTERIOR DOOR HAS A BLACK SCRATCH ON THE DOOR.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND THE AREA.

LABOR .20

**Labor**

Job #	Description	Hours	Total
2	REPAIR	0.20	33.00
<b>Subtotal for Job #2:</b>			<b>33.00</b>

**Job #3 - Warranty**

COMPLAINT: INTERIOR CABINET STILE HAS STAPLE HOLES.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND BLEND AREA.

LABOR .20

**Labor**

Job #	Description	Hours	Total
3	REPAIR	0.20	33.00

Customer #: 76295  
 HAEHNER, CARL



Subtotal for Job #3: 33.00

**Job #4 - Warranty**

COMPLAINT: WRINKLE IN THE LINO FLOORING IN THE LIVING AREA.

CAUSE: WRINKLE DEVELOPED IN LINO FLOORING.

CORRECTION: REPAIR THE LINO FLOOR TO LAY FLAT AND CORRECTLY. TECH WILL USE HEAT TO MAKE PLIABLE AND THEN AREA WILL HAVE TO BE ROLLED.

LABOR 2.0

**Labor**

Job #	Description	Hours	Total
4	REPAIR LINO	2.00	330.00

Subtotal for Job #4: 330.00

Parts Total: 0.00  
 Labour Total: 445.50  
 Sublet Total: 0.00  
 Extras Total: 0.00

**WORK ORDER TOTAL: 445.50**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 14 May 2025

W/O: 25408



Customer #: 76295  
HAEHNER, CARL

