



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25438



WO #: 25438 (Appointment Date: 12 MAY 2025 - Time: 11:00am)

Customer: 92766 - McCLELLAND, RON  
 Address:  
 , TN

Home Phone: (719) 221-6625

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #:  
 Stock Desc: 2022 A COACHMAN MIRADA  
 MDA29FW  
 Model: MDA29FW  
 Serial #: 5ZTAMDU02NM517003  
 Chassis #: 1F65F5DN8M0A03874  
 Mileage:13209  
 Key #:  
 Req'n #:  
 License #:  
 Trim:

Purchase Date:  
 Date In: 12 MAY 25  
 Promise Date:  
 Promise Time:  
 Schedule Date:  
 Completed:  
 Warr. Date:

**Job #1 - External**

COMPLAINT: CS THAT THEY HAVE A LEVELING TSB AND THE R/R JACK IS NOT WORKING CORRECTLY (TSB51-1576)

CAUSE: TSB# 85-001-2022  
 ALL 4 JACKS (BOTH FRONT AND REAR)  
 NEED REPLACED PER TSB INSTRUCTIONS.

CORRECTION: REPLACE ALL 4 JACKS AND TEST  
 LABOR 4.0 TOTAL FOR ALL FOUR JACKS.

**Parts**

Part #	Description	Qty	Price	Total
80028A	AUTO TRANSMISSION FLUID	2.00	N/C	N/C
F100388233	JACK, LEVELING, GENERATION 2 8K - LIPPERT #372892	4.00	N/C	N/C
F100084285	ELBOW, HYDRAULIC FITTING, 90 DEGREE O-RING FACE SEAL , FOR LIPPERT JACK SYSTEM 693826 - LIPPERT #141610	4.00	N/C	N/C
F100388551	FITTING, "T" FOR HYDRAULIC LEVELING SYSTEM - LIPPERT #143108	4.00	N/C	N/C

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
SHF	SHIPPING/FREIGHT FEE	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: A/C GE SOFT START RECALL FRONT A/C

CAUSE: RECALL 24V771

CORRECTION: INSPECTION ONLY  
 LABOR .25

**Labor**

Job #	Description	Hours	Total
2	INSPECTION ON A/C NUM 1	0.25	41.25

Customer #: 92766  
 McCLELLAND, RON



Subtotal for Job #2: 41.25

**Job #3 - External**

CS THAT THE SLIDE IS NOT HITTING THE STOPS CORRECTLY

Subtotal for Job #3: 0.00

**Job #4 - External**

TEST BATTERIES

Subtotal for Job #4: 0.00

**Job #5 - External**

CUS HAS MILITARY DISCOUNT

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: A/C GE SOFT START RECALL REAR A/C RECALL

CAUSE: RECALL 24V771

CORRECTION: INSPECTION ONLY

LABOR .25

**Labor**

Job #	Description	Hours	Total
6	INSPECTION ON A/C NUM 2	0.25	41.25

Subtotal for Job #6: 41.25

Parts Total: 0.00

Labour Total: 82.50

Sublet Total: 0.00

Extras Total: 0.00

**WORK ORDER TOTAL: 82.50**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 17 Jun 2025

Customer Signature : \_\_\_\_\_



Customer #: 92766  
McCLELLAND, RON

