



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25446



WO #: 25446

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11112

Stock Desc: 2025 TT KZ-RV SPORTSMEN CLASS
130RD

Model: 130RD

Serial #: 4EZTK1313S5046475

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 13 MAY 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: BATHROOM CABINET DOOR HAS A CHIP IN IT.

CAUSE: NOTED ON DAF.

CORRECTION: FILL, COLOR AND BLEND AREA.
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SCRATCH ON CABINET OVER THE BED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: NAIL HOLES AND WET PUDDY OVER BED ON THE STILE.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN EXTRA PUDDY OFF
COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SEAM TAPE OVER KITCHEN TABLE IS DISCOLORED AND STAINED.

CAUSE: NOTED ON DAF

CORRECTION: REPLACE SEAM TAPE
LABOR .20

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

W/O: 25446

Job #5 - Warranty

COMPLAINT: SCRATCH/HOLES OVER FILLED ON CABINET DOOR UNDER KITCHEN SINK

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20

Subtotal for Job #5: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00



I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 May 2025

Customer Work Order

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

