

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0049080  
 TRI AM RV CENTER OF EAST TN  
 1202 IDELL ROAD (I-81 EXIT 23)  
 BULLS GAP, TN 37711  
 USA

CLAIM STATUS Paid  
 CLAIM 2311636  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TCRS22SS234441  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 020 / 020  
 ITEM # CRT40CRS  
 DEALER RO # 25459  
 CLAIM START DATE 05/27/2025  
 CLAIM END DATE 05/28/2025

Labor rate: \$165.00

**OWNER INFORMATION**

ELAINE THOMPSON  
 10 MCGREGOR PL  
 Johnson City, TN 37604  
 USA

Retail Date of Purchase 04/29/2025

WARRANTY EXPIRATION DATE

04/29/2026

**Claim Line Details**

**Labor**

Line# 1      **Operation Code**      **Operational Description**  
 30-100-24-00-001054      Kitchen/Galley Countertop - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : ashlee@dealer-advisors.com, 2025-05-27 09:27:08 :: Complaint: Kitchen counter tops have several scratches on all of them Cause: Counter had scratches when installed Correction: Compound all counters (4) and then polish

<b>Model#</b>	<b>Dlr Sub Hrs</b>	2.00	<b>Sub Labor Amt</b>	\$330.00
<b>Serial#</b>	<b>Appr Hrs</b>	2.00	<b>Appr Labor Amt</b>	\$330.00

**Notes**  
 AUTHORIZED

**Part**

Line# 1	<b>Item #</b>	<b>Description</b>			
	USERPART	Gel gloss 64 oz			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	Sub Qty 1.00	Sub Dlr Price \$27.21	Sub Freight	\$0.00	
	Appr Qty 1.00	Appr Dlr Price \$27.21	Appr Freight	\$0.00	

**Notes**

Line# 2	<b>Item #</b>	<b>Description</b>			
	USERPART	Shop supplies			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	Sub Qty 1.00	Sub Dlr Price \$5.00	Sub Freight	\$0.00	
	Appr Qty 1.00	Appr Dlr Price \$5.00	Appr Freight	\$0.00	

**Notes**

<b>Submitted</b>	Labor Amt	\$330.00	<b>Approved</b>	Labor Amt	\$330.00
	Parts & Freight	\$32.21		Parts & Freight	\$32.21
	Total	\$362.21		Total	\$362.21

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE  
 All repairs described have been inspected and are satisfactory.