



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25485



WO #: 25485

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11110

Stock Desc: 2025 TT KZ-RV SPORTSMEN CLASS
191BHK

Model: 191BHK

Serial #: 4EZTK1815S5046244

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 21 MAY 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date:

Job #1 - Warranty

COMPLAINT: PAINT IS CHIPPED ON MED CABINET IN THE BATHROOM

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND BLEND AREA(S)

LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: INTERIOR SLIDE FASCIA HAS NAIL HOLES ACROSS THE TOP AND BOTH LEGS

CAUSE: NOTED ON DAF

CORRECTION: COLOR FILL AND BLEND AREA

LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SLIDE FASCIA INSERT IS COMING LOOSE, THE INSERT IS TOO LONG AND WILL NOT STAY IN PLACE.

CAUSE: NOTED ON DAF

CORRECTION: INSERT NEEDS TO BE CUT TO FIT AND RESECURED IN PLACE

LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SMALL HOLE/CHIP ON WALL LANE ON THE SLIDE

CAUSE: NOTED ON DAF

CORRECTION: NEED TO FILL THE SPOT AFTER IT DRIES SAND AREA, THEN COLOR AND BLEND

LABOR .30

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



W/O: 25485

Subtotal for Job #4: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 21 May 2025



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Customer Work
Order

