



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25598
 Promised Date: 25 JUN 25



WO #: 25598 (Appointment Date: 18 JUN 2025 - Time: 09:00am)

Customer: 91789 - OSBORNE, HOMER
 Address: 141 LAKEFIELD CIR
 KINGSPOINT, TN
 37663

Home Phone: (423) 335-0454

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 10786
 Stock Desc: 2023 CT FOREST RIVER
 ROCKWOOD CAMP 2514F
 Model: 2514F
 Serial #: 4X4CFMU16PD319034
 Chassis #:
 Mileage:0
 Key #: 1359
 Req'n #:
 License #:
 Trim:

Purchase Date: 27 JUN 24
 Date In: 11 JUN 25
 Promise Date: 30 JUN 25
 Promise Time: 09:00am
 Schedule Date:
 Completed: 30 JUN 25
 Warr. Date: 27 JUN 24

Job #1 - Warranty

CUS WARRANTY ISSUES WILL DESCRIBE AT DROP OFF

Subtotal for Job #1: 0.00

Job #2 - Warranty

CS THAT AWNING ENDS WILL NOT STAY IN PLACE WHEN TRYING TO SET IT UP CUST WANTS
 UPGRADED AWNING WILL PAY THE EXTRA WANTS A CRANK OUT STYLE (DONT WANT THE ONE
 THATS ON IT)

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: PANEL NEXT TO THE SLIDE IS COMING LOOSE

CAUSE: PANEL CAME LOOSE

CORRECTION: RESECURE PANEL BACK IN PLACE
 LABOR .20

Labor

Job #	Description	Hours	Total
3	RESECURED PANEL IN PLACE	0.20	33.00

Subtotal for Job #3: 33.00

Job #4 - Warranty

COMPLAINT: CS THAT THE CANVAS IS COMING LOOSE ON THE SLIDE OUT MIGHT NEED EXTRA
 HARDWARE TO HOLD CANVAS IN PLACE

CAUSE: SCREW NEEDS TO BE RELOCATED FOR CANVAS

CORRECTION: REMOVE AND RELOCATE SCREW TO HOLD CANVAS IN CORRECT PLACE
 LABOR .20

Labor

Job #	Description	Hours	Total
4	REPAIRED AREA	0.75	123.75

Customer #: 91789
 OSBORNE, HOMER



Subtotal for Job #4: 123.75

Job #5 - Warranty

COMPLAINT: CS THAT THERE IS A SCREW ABOVE THE DOOR THAT IS COMING LOOSE AND IS NOT HOLDING CANVAS IN PLACE

CAUSE: SCREW IS NOT SECURE IN PLACE ALLOWING CANVAS TO COME DOWN IN THIS AREA

CORRECTION: RESECURE SCREW IN PLACE
LABOR .20

Labor

Job #	Description	Hours	Total
5	SECURED SCREW BACK IN PLACE AT CANVAS	0.75	123.75

Subtotal for Job #5: 123.75

Parts Total: 0.00
 Labour Total: 280.50
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 280.50

 I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
 X _____

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 30 Jun 2025

W/O: 25598
Promised Date: 30 JUN 25



Customer #: 91789
OSBORNE, HOMER

