

**Pre-Authorization**

Pre-Authorization number PA03874926 Reference no: 25672 Status: Approved Approved by martm Approved date 7/7/2025  
 Servicing Name Address VIN Retail sold on Dealer

8140 Tri-AM RV Center of East TN  
 Tri-AM RV Center of East TN  
 1202 Idell Rd  
 Bulls Gap, TN 37711  
 4YDTATG1XT8920098

Nu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
mbe	operation								
r of									
1	2102814B	Wall - Metal Siding	0.00	6.00	10.00		1	0.50	Complaint:Scatched metal on NDS of the unit, damage is all down the side of this unit on the metal Cause:Damaged when installed. Noted on DAF Correction:Remove and replace the damaged metal
2	2102808B	Wall - Metal Siding	0.00	4.00	4.00		1	0.50	Complaint:Metal is scatched and damaged on back of unit Cause:Done at factory, noted on DAF Correction:Remove and replace damaged metal on the back of the unit  KRV-Approved to replace
3	3102509A	Dinette Seat Base	0.00	0.20	0.20		1	0.20	Complaint:Side panel of the kitchen seating has paint rubbed off Cause:Noted on DAF Correction:Color, blend, and clean area
4	4201814A	Awning - Main - H	0.00	0.20	0.20		1	0.50	Complaint:When awning is retracted, it will extend Cause:Switch installed backwards to the labels. Noted on DAF Correction:Install switch to correct position
5	4138014A	Furnace - Suburb	0.00	1.00	0.30		1	0.30	Complaint:Furnace is in sideways and the cover is crooked Cause:Installed sideways at the factory, noted on DAF Correction:Remove cover and furnace, reinstall correctly
6	3202008A	Panel - Interior W	0.00	0.20	0.20		1	0.10	Complaint:Hole in wall at the bathroom door Cause:Noted on DAF Correction:Fill, color, and clean area
					<u>14.90</u>				

Pre-Authorization number PA03874926

For paper claims only use one pre-authorization number per warranty claim for  
 Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company