



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25672



WO #: 25672

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11142
Stock Desc: 2026 TT DUTCHMEN ASPEN TRAIL
MINI 17BH
Model: 17BH
Serial #: 4YDTATG1XT8920098
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 25 JUN 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: SCRATCHED METAL ON NDS OF THE UNIT, DAMAGE IS ALL DOWN THE SIDE OF THIS UNIT ON THE METAL

CAUSE: DAMAGED WHEN INSTALLED
NOTED ON DAF

CORRECTION: REPLACE THE DAMAGED METAL
REMOVE AND REPLACE THE DAMAGED METAL
LABOR 6.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: METAL IS SCRATCHED AND DAMAGED ON THE BACK OF THE UNIT

CAUSE: DONE AT FACTORY, NOTED ON DAF

CORRECTION: REMOVE AND REPLACE DAMAGED METAL ON THE BACK OF THE UNIT
LABOR 4.0

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SIDE PANEL OF THE KITCHEN SEATING HAS PAINT RUBBED OFF

CAUSE: NOTED ON DAF

CORRECTION: COLOR, BLEND AND CLEAN AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: WHEN YOU RETRACK THE AWING IT WILL EXTEND

CAUSE: SWITCH INSTALLED BACKWARDS TO THE LABELS
NOTED ON THE DAF

CORRECTION: INSTALL SWITCH TO CORRECT POSITION

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



LABOR .20

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: FURNACE IS IN SIDEWAYS AND THE COVER IS CROOKED

CAUSE: INSTALLED SIDEWAYS AT THE FACTORY
NOTED ON DAF

CORRECTION: REMOVE COVER AND FURNACE, REINSTALL CORRECTLY
LABOR 1.0

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: SMALL HOLE IN WALL AT THE BATHROOM DOOR

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND CLEAN AREA
LABOR .10

Subtotal for Job #6: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 25 Jun 2025

W/O: 25672



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

