



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 25677



WO #: 25677

Customer: 92693 - GIBSON, NATALIE
 Address: 728 SAN MARTIN RD
 DANDRIDGE, TN
 37725

Home Phone: (865) 274-3520

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11119

Stock Desc: 2025 TT KZ-RV CONNECT SE

301BHKSE

Model: 301BHKSE

Serial #: 4EZTL3122S4046073

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 28 JUN 25

Date In: 26 JUN 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 15 AUG 25

Warr. Date: 28 JUN 25

Job #1 - Warranty

COMPLAINT: ENTRY DOOR IS SCRATCHED IN SEVERAL PLACES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE ENTRY DOOR

LABOR 1.0

Labor

Job #	Description	Hours	Total
1	REPLACED DOOR	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
162695	ENTRANCE DOOR FULL GLASS W/BLK FRAME	1.00	567.99	567.99

Other Services

Code	Description	Qty	Price	Total
SHF	SHIPPING/FREIGHT FEE	1.00	165.00	165.00

Subtotal for Job #1: 907.99

Job #2 - Warranty

COMPLAINT: SHOWER SURROUND IS BOWED OUT AT THE TOP LEFT SIDE

CAUSE: SURROUND IS NOT SECURE TO THE WALL

NOTED ON DAF

CORRECTION: ADD A RIVET TO THE SHOWER SURROUND

LABOR .30

Labor

Job #	Description	Hours	Total
2	ADDED RIVET	0.50	87.50

Other Services

Code	Description	Qty	Price	Total
NII	SHOP SUPPLY	1.00	3.99	3.99

Subtotal for Job #2: 91.49

Job #3 - Warranty

COMPLAINT: SLIDE STILE AND FASCIA HAS SEVERAL NAIL HOLES

Customer #: 92693
 GIBSON, NATALIE



CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND CLEAN AREA
LABOR .20

Labor

Job #	Description	Hours	Total
3	FILL AND COLOR	0.10	17.50

Subtotal for Job #3: 17.50

Job #4 - Warranty

COMPLAINT: MOLDING TO THE RIGHT OF THE CLOSET IS LOOSE AND NOT SECURED IN PLACE

CAUSE: NOTED ON DAF

CORRECTION: SECURE THE MOLDING BACK IN CORRECT PLACE. COLOR AND BLEND MARKS
FROM THE MOLDING
LABOR .30

Labor

Job #	Description	Hours	Total
4	COLOR AND BLEND	0.30	52.50

Subtotal for Job #4: 52.50

Parts Total:	567.99
Labour Total:	332.50
Sublet Total:	0.00
Extras Total:	168.99

WORK ORDER TOTAL: 1,069.48

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 15 Aug 2025

W/O: 25677



Customer #: 92693
GIBSON, NATALIE

