



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 25677



WO #: 25677

Customer: 92693 - GIBSON, NATALIE
Address: 728 SAN MARTIN RD
DANDRIDGE, TN
37725

Home Phone: (865) 274-3520

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11119

Stock Desc: 2025 TT KZ-RV CONNECT SE
301BHKSE

Model: 301BHKSE

Serial #: 4EZTL3122S4046073

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 28 JUN 25

Date In: 26 JUN 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 28 JUN 25

Job #1 - Warranty

COMPLAINT: ENTRY DOOR IS SCRATCHED IN SEVERAL PLACES

CAUSE: NOTED ON DAF

CORRECTION: REPLACE ENTRY DOOR
LABOR 1.0

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHOWER SURROUND IS BOWED OUT AT THE TOP LEFT SIDE

CAUSE: SURROUND IS NOT SECURE TO THE WALL
NOTED ON DAF

CORRECTION: ADD A RIVET TO THE SHOWER SURROUND
LABOR .30

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SLIDE STILE AND FASCIA HAS SEVERAL NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL COLOR AND CLEAN AREA
LABOR .20

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: MOLDING TO THE RIGHT OF THE CLOSET IS LOOSE AND NOT SECURED IN PLACE

CAUSE: NOTED ON DAF

CORRECTION: SECURE THE MOLDING BACK IN CORRECT PLACE. COLOR AND BLEND MARKS
FROM THE MOLDING
LABOR .30

Customer #: 92693
GIBSON, NATALIE



Subtotal for Job #4: 0.00

W/O: 25677

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Jun 2025



Customer Work Order

Customer #: 92693
GIBSON, NATALIE

