



Phone: (423) 235-1167  
Toll Free: (877) 635-1167  
Fax: (423) 235-1176

1202 Idell Road  
Bulls Gap, TN 37711

W/O: 25791



WO #: 25791

Customer: 47602 - TRIAM RV CENTER-EAST TN  
Address: 1202 IDELL ROAD  
BULLS GAP, TN  
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11113

Stock Desc: 2025 TT KZ-RV SPORTSMEN CLASS  
191BHK

Model: 191BHK

Serial #: 4EZTK1811S5046256

Chassis #:

Mileage: 0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 22 JUL 25

Date In: 18 JUL 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 22 JUL 25

**Job #1 - Warranty**

COMPLAINT: NEGATIVE WIRE FOR BATTERY MISSING

CAUSE: NOTED ON DAF

CORRECTION: REPLACE NEGATIVE WIRE  
LABOR .50

**Subtotal for Job #1: 0.00**

**Job #2 - Warranty**

COMPLAINT: STILE ON BUNK BED HAS A SPOT

CAUSE: NOTED ON DAF

CORRECTION: CLEAN, COLOR AND BLEND AREA  
LABOR .20

**Subtotal for Job #2: 0.00**

**Job #3 - Warranty**

COMPLAINT: BATHROOM DOOR HAS A CHIP ON IN

CAUSE: NOTED ON DAF

CORRECTION: REPLACE BATHROOM DOOR  
LABOR .50

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: BATHROOM MED CABINET HAS SPOTS OF PAINT CHIPPED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA  
LABOR .20

Customer #: 47602  
TRIAM RV CENTER-EAST  
TN,



Subtotal for Job #4: 0.00

**Job #5 - Warranty**

COMPLAINT: PAINT CHIP ON CORNER STILE NEXT TO FRIDGE

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA  
LABOR .20

Subtotal for Job #5: 0.00

**Job #6 - Warranty**

COMPLAINT: WALL LUAN NEXT TO THE FRIDGE IS SPOTTED AND HAS SEVERAL NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREAS  
LABOR .30

Subtotal for Job #6: 0.00

**Job #7 - Warranty**

COMPLAINT: INT SLIDE FASCIA AND LEGS HAVE NAIL AND STAPLE HOLES IN SEVERAL DIFF PLACES

CAUSE: NOTED ON THE DAF

CORRECTION: FILL, COLOR AND CLEAN THE AREA  
LABOR .20

Subtotal for Job #7: 0.00

**Job #8 - Warranty**

COMPLAINT: THE PANEL TO THE LEFT OF THE ENTRY DOOR HAS PAINT SMUDGES AND NAIL HOLES

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND THE AREAS  
LABOR .30

Subtotal for Job #8: 0.00

Parts Total: 0.00  
Labour Total: 0.00  
Sublet Total: 0.00  
Extras Total: 0.00

**WORK ORDER TOTAL: 0.00**

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : \_\_\_\_\_

Date: 18 Jul 2025



Customer #: 47602  
TRI-AM RV CENTER-EAST  
TN,

