

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0049080	CLAIM STATUS	Authorized
TRI AM RV CENTER OF EAST TN		CLAIM	2410038
1202 IDELL ROAD (I-81 EXIT 23)		CLAIM ORIGIN	WEB
BULLS GAP, TN 37711		ORIGINAL CLAIM ID	
USA		VIN	4X4TSAS24SJ048328
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$165.00	SITE/WAREHOUSE	003 / 003A
OWNER INFORMATION		ITEM #	SAT40DUPLEX
MARK HARRIS		DEALER RO #	25948
624 DRYDEN HEIGHTS DR		CLAIM START DATE	08/21/2025
Dryden, VA 24243		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/19/2025	WARRANTY EXPIRATION DATE	06/19/2026

Claim Line Details

Labor				
Line# 1	Operation Code	Operational Description		
	40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/ Electrical		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-08-21 13:39:30 :: Complaint: Plugs inside bedroom are inop Cause: Found the wires are reversed under the bed at the molex connector Correction: Remove and reinstall wires in correct place on molex connector			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$49.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$49.50
Notes				
Labor				
Line# 2	Operation Code	Operational Description		
	20-46-01-00-000727	Window Screen Clips - Exterior/Windows/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ashlee@dealer-advisors.com, 2025-08-21 13:41:35 :: Complaint: Curtain clip over window is missing Cause: Customer stated the clip has never been in the unit, only one clip above the window Correction: Replace clip			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$16.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$16.50
Notes				

Submitted	Labor Amt	\$66.00	Approved	Labor Amt	\$66.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$66.00		Total	\$66.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.