



Phone: (423) 235-1167  
 Toll Free: (877) 635-1167  
 Fax: (423) 235-1176

1202 Idell Road  
 Bulls Gap, TN 37711

W/O: 25948  
 Promised Date:  
 26 SEP 25



WO #: 25948 (Appointment Date: 19 AUG 2025 - Time: 09:00am)

Customer: 70226 - HARRIS, MARK  
 Address: 624 DRYDEN HEIGHTS DRIVE  
 DRYDEN, VA  
 24243

Home Phone: (423) 579-8241

Work Phone:

Author:SPD

Location: IH

Invoice #:

Stock #: 11118

Stock Desc: (11118) 2025 FOREST RIVER

SANDPIPER 40DUPLEX

Model: 40DUPLEX

Serial #: 4X4TSAS24SJ048328

Chassis #:

Mileage:0

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 19 JUN 25

Date In: 19 AUG 25

Promise Date: 30 SEP 25

Promise Time: 09:00am

Schedule Date:

Completed:

Warr. Date: 19 JUN 25

**Job #1 - Warranty**

COMPLAINT: PLUGS INSIDE BEDROOM ARE INOP

CAUSE: FOUND THE WIRES ARE REVERSED UNDER THE BED AT THE MOLEX CONNECTOR

CORRECTION: REMOVE AND REINSTALL WIRES IN CORRECT PLACE ON MOLEX CONNECTOR  
 LABOR .30

**Subtotal for Job #1: 0.00**

**Job #3 - External**

SC 1099 HWY 25E NEWPORT TN

**Other Services**

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

**Subtotal for Job #3: 0.00**

**Job #4 - Warranty**

COMPLAINT: CURTAIN CLIP OVER WINDOW IS MISSING

CAUSE: CUSTOMER STATED THE CLIP HAS NEVER BEEN IN THE UNIT, ONLY ONE CLIP ABOVE THE WINDOW

CORRECTION: REPLACE CLIP  
 LABOR .05

**Subtotal for Job #4: 0.00**

Parts Total: 0.00  
 Labour Total: 0.00  
 Sublet Total: 0.00  
 Extras Total: 0.00  
**WORK ORDER TOTAL: 0.00**

Customer #: 70226  
 HARRIS, MARK



-----  
I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.  
X \_\_\_\_\_  
-----

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 21 Aug 2025

Customer Signature : \_\_\_\_\_

W/O: 25948  
Promised Date: 30 SEP 25



Customer Work  
Order

Customer #: 70226  
HARRIS, MARK

