



# KEYSTONE

## Pre-Authorization

Pre-Reference 2595 Status Appr  
 Authorization UTH6 no. 8 oved  
 number 908  
 (PA0  
 3901  
 626)

Service Dealer 8140 Name Tri-AM RV Center of East TN Address 1202 Idell Rd Bulls Gap, TN 37711 VIN 4YDTATN26T8920207 Retail sold on

Root	Sub	Approved	Actual	Base				
Operation	Description	Sublet	Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
1102708B	Center Cap	0	0.5	0.5		1	0.2	<b>Complaint:</b> Dust cap on driver side rear axle is damaged <b>Cause:</b> Noted on DAF <b>Correction:</b> Replace the dust cap and center insert
3500208A	Vinyl Flooring - Repair - per square yard	0	1	0.6		1	0.6	<b>Complaint:</b> Lino flooring through the living and kitchen area has black rubber marks across it in several spots <b>Cause:</b> Noted on DAF <b>Correction:</b> Area have to be cleaned/scrubbed off, this will not come up with just water

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



# KEYSTONE

Root			Sub	Approved	Actual		Base	
Operation	Description	Sublet	Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
3202008A	Panel - Interior Wall - Repair	0	0.2	0.1	_____	1	0.1	<b>Complaint:</b> Stain on bathroom wall next to hanger hook <b>Cause:</b> Noted on DAF <b>Correction:</b> Clean area and touch up color if needed
3202008B	Panel - Interior Wall - Replace	0	2	1.5	_____	1	1	<b>Complaint:</b> Wall panel at the hidden pantry is damaged <b>Cause:</b> Noted on DAF <b>Correction:</b> Remove and replace panel. Damage is eye level, fill and color will not fix issue
Pre-Authorization number: PREAUTH6908			2.7		_____			

For paper claims only use one pre-authorization number per warranty claim form.

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.