

APPOINTMENT DATE		8/22/2025		VEHICLE ARRIVED		8/22/2025		WSO DATE PREPARATION			CLAIM STATUS			Approved		WARRANTY CLAIM No		
REPAIR COMPLETION DATE		8/26/2025		CUSTOMER NOTIFIED			VEHICLE PICKED UP			CREDIT DATE		8/26/2025		CREDIT NUMBER		KZ615626		
RV SERIAL NUMBER		4EZTK1815S5046664			MAKE			CLASSIC		MODEL		160QB		YEAR		2025		
DEALER					CUSTOMER					FACTORY USE ONLY								
NUMBER		TRI030		LABOR RATE		\$175.00		FEE RATE		15.00		CONTACT			ACCT. #		DENIAL CODE	
NAME		Tri-Am RV Center of E. Tn, Inc			PHONE		ADDRESS			PHONE		EQUIP. SER. #		EQUIP. SER. #				
ADDRESS		1202 Idell Road										EQUIP. MODEL		EQUIP. MODEL				
CITY		Bulls Gap		STATE		TN		ZIP		37711		CITY		STATE		ZIP		
												EQUIP. MFR.		EQUIP. MFR.				

WARRANTY CLAIM # KZ615626	JOB OPERATION 1	Top cabinet door left of the entry color fill needs blended. This spot makes the cabinet look like it has a bad spot	OPERATION CODE		5538		AUTHORIZATION #		CT5082207						
			HOURS		0.10		AMOUNT		\$17.50						
			SUBLET				SUPPLIER NAME		A KZ WARRANTY						
			STATUS		Approved										
CAUSE Noted on DAF			LABOR		\$17.50		PARTS		MARK UP		FREIGHT		SUBLET		
			PART #				CHARGEBACK #				Dup		N		
			JOB OPERATION DENIAL CODE				INITIALS								
			REMEDY												
			Clean, color, and blend												
PART NUMBER		PART DESCRIPTION				RETURN TAG #		QUANTITY		UNIT		TOTAL PARTS		ADJUSTED TOTAL	
						SUB-TOTAL:		LABOR		\$17.50		PARTS		\$0.00	

WARRANTY CLAIM # KZ615626	JOB OPERATION 2	Wood valance at the table has holes	OPERATION CODE		6606		AUTHORIZATION #		CT5082208						
			HOURS		0.10		AMOUNT		\$17.50						
			SUBLET				SUPPLIER NAME		A KZ WARRANTY						
			STATUS		Approved										
CAUSE Noted on DAF			LABOR		\$17.50		PARTS		MARK UP		FREIGHT		SUBLET		
			PART #				CHARGEBACK #				Dup		N		
			JOB OPERATION DENIAL CODE				INITIALS								
			REMEDY												
			Fill, color, and blend												
PART NUMBER		PART DESCRIPTION				RETURN TAG #		QUANTITY		UNIT		TOTAL PARTS		ADJUSTED TOTAL	
						SUB-TOTAL:		LABOR		\$17.50		PARTS		\$0.00	

WARRANTY CLAIM # KZ615626	JOB OPERATION 3	Wall panel at bathroom mirror has a stain	OPERATION CODE 5521		AUTHORIZATION # CT5082209			
			HOURS 0.10	AMOUNT \$17.50	SUBLET			
			SUPPLIER NAME A KZ WARRANTY		STATUS Approved			
CAUSE Noted on DAF			LABOR \$17.50	PARTS	MARK UP	FREIGHT	SUBLET	
			PART #		CHARGEBACK #		Dup N	
			JOB OPERATION DENIAL CODE				INITIALS	
			REMEDY					
			Clean and touch up color if needed					
PART NUMBER	PART DESCRIPTION		RETURN TAG #	QUANTITY	UNIT	TOTAL PARTS	ADJUSTED TOTAL	
			SUB-TOTAL:	LABOR \$17.50	PARTS	\$0.00		

WARRANTY CLAIM # KZ615626	JOB OPERATION 4	Wall panel at fridge has several holes	OPERATION CODE 5521		AUTHORIZATION # CT5082210			
			HOURS 0.20	AMOUNT \$35.00	SUBLET			
			SUPPLIER NAME A KZ WARRANTY		STATUS Approved			
CAUSE Noted on DAF			LABOR \$35.00	PARTS	MARK UP	FREIGHT	SUBLET	
			PART #		CHARGEBACK #		Dup N	
			JOB OPERATION DENIAL CODE				INITIALS	
			REMEDY					
			Fill, color, and blend area					
PART NUMBER	PART DESCRIPTION		RETURN TAG #	QUANTITY	UNIT	TOTAL PARTS	ADJUSTED TOTAL	
			SUB-TOTAL:	LABOR \$35.00	PARTS	\$0.00		

COMMENTS BC 8/21 Part pricing subject to change at final approval.	SUBMIT DATE 8/26/2025	TOTAL PARTS	\$0.00	\$0.00
	PREPARED BY Ashlee Olsen	MARK UP ALLOWANCE	\$0.00	
		FREIGHT		
		GST		
		BROKERAGE		
		TOTAL LABOR	\$87.50	
		SUBLET	\$0.00	
		TOTAL	\$87.50	\$87.50

TERMS AND CONDITIONS	I acknowledge that the services listed above have been completed, and to the extent they may be covered under warranty, I authorize KZRV, LP. to make payments to the servicing dealer.
----------------------	---

I hereby authorize you to perform this service at your regular prices and terms. You may operate my auto, trailer, or motor home to test, inspect or deliver same at my risk. I agree that you assume no liability for loss or damage to my trailer, auto, or motor home or the contents of either from any cause not the direct fault of your company.

AUTHORIZED BY