

# DAF: Dealer Unit Inspection Form



FOREST RIVER

Forest River, Inc.  
201 W Elm Street  
Millersburg, IN 46543  
USA

*Warranty  
w/ b 26037*

Short VIN/Unit: RLD466795

Model/Item: RLT2511S

Dealer: TRI AM RV CENTER OF

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect **within 24 hours after the secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months from delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

Keys	<input checked="" type="radio"/> Yes	<input type="radio"/> No
BBQ Grill	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Power Cord	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Warranty Packet	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Sink cover	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Jack Handles	<input checked="" type="radio"/> Yes	<input type="radio"/> No
TV 1	<input checked="" type="radio"/> Yes	<input type="radio"/> No
TV 2	<input type="radio"/> Yes	<input checked="" type="radio"/> No
Remotes	<input checked="" type="radio"/> Yes	<input type="radio"/> No

List Any Miscellaneous Comments Regarding Condition of Unit:

*① Drawer in bedroom sideways,  
② Kitchen cabinets need adjusted above sink.  
③ ceiling strip over theater seating damaged.*

List Any Additional Missing Items:

Suggested areas to inspect:	
Unit Cleanliness	If no, explain:
Condition of Flooring	
Cabinetry Damage	If yes, explain:
Appliance Condition	
Furniture Tears/Stains	If yes, explain:
Frame/Chassis Condition	
Roof Components	
Roof Material	
Awning Fabric	
ODS/DS Walls & Graphics	
Unit Front & Graphics	
Unit Rear & Graphics	
Additional Notations	<i>Driver side front tire repaired by driver @ wal-mart. screw in tire DAF will be completed within the 3 days by dealer</i>

Unit/Underside has been washed by the Dealership

Yes No

Date Washed \_\_\_\_\_

Dealer Signature

*Stephanie Lewis*  
*[Signature]*

Date

*9-4-25*  
*9-4-25*

# DAF: Dealer Unit Inspection Form



FOREST RIVER

Forest River, Inc.  
201 W Elm Street  
Millersburg, IN 46543  
USA

Short VIN/Unit: RLD466795

Model/Item: RLT2511S

Dealer: TRI AM RV CENTER OF

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect **within 24 hours after the secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months from delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

Keys	Yes	No
BBQ Grill	Yes	No
Power Cord	Yes	No
Warranty Packet	Yes	No
Sink cover	Yes	No
Jack Handles	Yes	No
TV 1	Yes	No
TV 2	Yes	No
Remotes	Yes	No

List Any Miscellaneous Comments Regarding Condition of Unit:

List Any Additional Missing Items:

Suggested areas to inspect:	
Unit Cleanliness	If no, explain:
Condition of Flooring	
Cabinetry Damage	If yes, explain:
Appliance Condition	
Furniture Tears/Steins	If yes, explain:
Frame/Chassis Condition	
Roof Components	
Roof Material	
Awning Fabric	
ODS/DS Walls & Graphics	
Unit Front & Graphics	
Unit Rear & Graphics	
Additional Notations	Driver side front tire repaired by driver @ wal-mart screw in tire. DAF will be completed within the 3 days by dealer

Unit/Underside has been washed by the Dealership

Yes No

Date Washed

Dealer Signature

*Stephanie Jones*

Date

9-4-25

*RPA*

9-4-25