

APPOINTMENT DATE	9/15/2025	VEHICLE ARRIVED	9/15/2025	WSO DATE PREPARATION		CLAIM STATUS	Pre-Auth. Approved	WARRANTY CLAIM No	
REPAIR COMPLETION DATE		CUSTOMER NOTIFIED		VEHICLE PICKED UP		CREDIT DATE		CREDIT NUMBER	
RV SERIAL NUMBER	4EZTL3222R4030335	MAKE		CONNECT		MODEL	C302FBK	YEAR	2024
PURCHASE DATE		12/10/2024							
DEALER				CUSTOMER				FACTORY USE ONLY	
NUMBER	TRI030	LABOR RATE	\$175.00	FEE RATE	15.00	CONTACT	Patrick Muse	ACCT. #	
NAME		Tri-Am RV Center of E. Tn, Inc		PHONE		ADDRESS		PHONE	
ADDRESS		1202 Idell Road		373 Trimont Trail Apt 5		828-371-5461		EQUIP. SER. #	1000167447501 2400046
CITY		Bulls Gap		STATE	TN	ZIP	37711	EQUIP. MODEL	fcr10dcgta kr
CITY		Franklin		STATE	NC	ZIP	28734	EQUIP. MFR.	furrion

WARRANTY CLAIM # KZ617456	JOB OPERATION 1	Bathroom faucet on rear sink is squeaking when the handle turns and handle comes off	OPERATION CODE	3301	AUTHORIZATION #	JS5100310
CAUSE		Bathroom faucet handle has a manufacture defect and came off the base	HOURS	0.30	AMOUNT	\$52.50
			SUPPLIER NAME	RAMCO	STATUS	OpenPR
			LABOR	\$52.50	PARTS	
			MARK UP		FREIGHT	
			PART #		CHARGEBACK #	Dup N
			JOB OPERATION DENIAL CODE		INITIALS	
			REMEDY	Replace the faucet and water pressure test		
PART NUMBER	PART DESCRIPTION		RETURN TAG #	QUANTITY	UNIT	ADJUSTED TOTAL
SUB-TOTAL:			LABOR	\$52.50	PARTS	\$0.00

WARRANTY CLAIM # KZ617456	JOB OPERATION 2	Bottom fridge door is not closing correctly. Owner stated he has to lift up on the door to get it to close and stay. Customer was on an out of state trip and had to add a shim to help hold door up in place.	OPERATION CODE	8687	AUTHORIZATION #	JS5100311
CAUSE		Fridge door hinge has failed and not holding door in place or allowing door to open and close as designed	HOURS	0.70	AMOUNT	\$122.50
			SUPPLIER NAME	FURRIOR/LCI	STATUS	OpenPR
			LABOR	\$122.50	PARTS	
			MARK UP		FREIGHT	
			PART #		CHARGEBACK #	Dup N
			JOB OPERATION DENIAL CODE		INITIALS	
			REMEDY	Replace the lower fridge door		
			This is pre-auth for the R&R of the BOTTOM DOOR CATCH-2021124079 : C-FCR10DCDTA-031 and ADJUST DOOR			
PART NUMBER	PART DESCRIPTION		RETURN TAG #	QUANTITY	UNIT	ADJUSTED TOTAL
SUB-TOTAL:			LABOR	\$122.50	PARTS	\$0.00

COMMENTS	SUBMIT DATE	TOTAL PARTS	\$0.00	\$0.00
	PREPARED BY	MARK UP ALLOWANCE	\$0.00	
	FREIGHT			

TRI - AM RV CENTER
(260) 768-4016
1202 IDELL ROAD
BULLS GAP TN 37711


2 LBS

DWT: 8,8,8

SHIP TO:

KZ - RV INC -
(260) 768-4016
9270 W US 20

SHIPSHEWANA IN 46565



IN 465 9-03



UPS GROUND

TRACKING #: 1Z 660 241 03 7135 9578



BILLING: P/P

REF 1:KZ617466

WS 28.0.700 Zebra ZP 460 45.0A 11/2025



SEE NOTICE ON REVERSE regarding UPS Terms, and notice of limitation of liability. Where allowed by law, shipper authorizes UPS to act as forwarding agent for export control and customs purposes. If exported from the US, shipper certifies that the commodities, technology or software were exported from the US in accordance with the Export Administration Regulations. Diversion contrary to law is prohibited.

For information about UPS's privacy practices or to opt out from the sale of personal information, please see the UPS Privacy Notice at www.ups.com
R&D R 0825