



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26144



WO #: 26144

Customer: 47602 - TRIAM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11220
Stock Desc: 2026 FW FOREST RIVER CEDAR
CREEK 29RL
Model: 29RL
Serial #: 4X4FCRE21TS235364
Chassis #:
Mileage: 0
Key #:
Req'n #:
License #:
Trim:

Purchase Date:
Date In: 01 OCT 25
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: CHIPS/SCRATCHES ON STILE AT LIVING ROOM TV

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .30

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: EXIT WINDOW HAS DAYLIGHT COMING THROUGH AT THE BOTTOM

CAUSE: NOTED ON DAF
OUTTER TRIM WAS NOT INSTALLED CORRECTLY

CORRECTION: REMOVE SET SCREWS ON INTERIOR TRIM RING AROUND THE WINDOW. THEN
RESECURE RING BACK IN CORRECT PLACE.
LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SCRATCH ON KITCHEN TABLE

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .40

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: FRIDGE DOOR SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE SCRATCHED DOOR AND REPLACE WITH NEW ONE
LABOR .50

Customer #: 47602
TRIAM RV CENTER-EAST
TN,



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: RED SCRAPES ON THE DOOR SIDE FRONT CAP OF THE UNIT AT ARRIVAL

CAUSE: THIS WAS NOTED ON THE DEALER ACCEPTANCE FORM

CORRECTION: FIBERGLASS WORK AND REPAIR AREA
LABOR 4.0

Subtotal for Job #5: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 01 Oct 2025

Customer Signature : _____

W/O: 26144



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

