



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26276



WO #: 26276 (Appointment Date: 31 OCT 2025 - Time: 09:00am)

Customer: 93228 - LAWSON, STEWART
Address:

Home Phone: 423-254-4315

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #:

Stock Desc: 2025 TT FOREST RIVER VIBE T19RB

Model: T19RB

Serial #: 4X4TVBU24ST154048

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 27 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 29 DEC 25

Warr. Date:

Job #1 - Warranty

COMPLETE WO 26033 IN SERV FOLDER

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHOWER FRAME HAS FALLEN UNDER THE COUCH

CAUSE: THE PULL CURTAIN CARTRIDGE CAME APART AND FELL OFF

CORRECTION: REPLACE THE SHOWER CURTAIN CARTRIDGE AND RESEAL THE AREA
LABOR 2.5

Labor

Job #	Description	Hours	Total
2	REPLACE SHOWER CURTAIN CARTRIDGE	1.50	247.50

Parts

Part #	Description	Qty	Price	Total
F100301790	BLACK SHOWER SCREEN 36X62	1.00	132.67	132.67
38-8555	SILICONE DAP CLEAR	1.00	11.91	11.91

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	67.92	67.92

Subtotal for Job #2: 460.00

Parts Total: 144.58

Labour Total: 247.50

Sublet Total: 0.00

Extras Total: 67.92

WORK ORDER TOTAL: 460.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93228
LAWSON, STEWART



Customer Signature : _____

Date: 29 Dec 2025

W/O: 26276

Customer Work
Order



Customer #: 93228
LAWSON, STEWART

