



Phone: (423) 235-1167
 Toll Free: (877) 635-1167
 Fax: (423) 235-1176

1202 Idell Road
 Bulls Gap, TN 37711

W/O: 26304



WO #: 26304 (Appointment Date: 31 OCT 2025 - Time: 12:00pm)

Customer: 69757 - HERRON, JEREMY
 Address: 395 LOOKOUT RIDGE DR
 NICKELSVILLE, VA
 24271

Home Phone: (276) 479-1278

Work Phone:
 Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11128

Stock Desc: 2026 TT KZ-RV CONNECT 313MK

Model: 313MK

Serial #: 4EZTL3326T4056880

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 23 JUL 25

Date In: 31 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed: 21 NOV 25

Warr. Date: 23 JUL 25

Job #1 - Warranty

COMPLAINT: UNIT IS LEAKING AROUND THE FRONT DOOR AND WALL IN BEDROOM
 TECH SEE WARRANTY FOR THE VIDEOS SENT IN FROM CUSTOMER PLEASE

CAUSE: TECH DETERMINED WHEN AWNING WAS INSTALLED THERE WAS NOT THE CORRECT
 AMOUNT OF SEALANT APPLIED. THIS ALLOWED WATER TO GET INSIDE ON THE INTERIOR OF
 THE UNIT.

CORRECTION: UNIT NEEDS TO COME INSIDE BUILDING, TURN OFF ALL POWER, REMOVE THE
 STANDING WATER, USE DEHUMIDIFIER AND DRY UNIT WITH HEAT. THEN ADD SEALANT WHERE
 NEEDED TO STOP WATER FROM ENTERING UNIT.

LABOR 1.0

Labor

Job #	Description	Hours	Total
1	COMPLETED WO	1.00	175.00

Parts

Part #	Description	Qty	Price	Total
38-8555	SILICONE DAP CLEAR	1.00	10.53	10.53

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	5.99	5.99

Subtotal for Job #1: 191.52

Parts Total: 10.53
 Labour Total: 175.00
 Sublet Total: 0.00
 Extras Total: 5.99
WORK ORDER TOTAL: 191.52

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 69757
 HERRON, JEREMY



Customer Signature : _____

Date: 21 Nov 2025

W/O: 26304

Customer Work Order



Customer #: 69757
HERRON, JEREMY

