



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 26304



WO #: 26304 (Appointment Date: 31 OCT 2025 - Time: 12:00pm)

Customer: 69757 - HERRON, JEREMY
Address: 395 LOOKOUT RIDGE DR
NICKELSVILLE, VA
24271

Home Phone: (276) 479-1278

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11128

Stock Desc: 2026 TT KZ-RV CONNECT 313MK

Model: 313MK

Serial #: 4EZTL3326T4056880

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 23 JUL 25

Date In: 31 OCT 25

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 23 JUL 25

Job #1 - Warranty

COMPLAINT: UNIT IS LEAKING AROUND THE FRONT DOOR AND WALL IN BEDROOM
TECH SEE WARRANTY FOR THE VIDEOS SENT IN FROM CUSTOMER PLEASE

CAUSE: TECH DETERMINED WHEN AWNING WAS INSTALLED THERE WAS NOT THE CORRECT AMOUNT OF SEALANT APPLIED. THIS ALLOWED WATER TO GET INSIDE ON THE INTERIOR OF THE UNIT.

CORRECTION: UNIT NEEDS TO COME INSIDE BUILDING, TURN OFF ALL POWER, REMOVE THE STANDING WATER, USE DEHUMIDIFIER AND DRY UNIT WITH HEAT. THEN ADD SEALANT WHERE NEEDED TO STOP WATER FROM ENTERING UNIT.
LABOR 1.0

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 69757
HERRON, JEREMY



Customer Signature : _____

Date: 06 Nov 2025

