

DAF: Dealer Unit Inspection Form



Forest River, Inc.
306 North Wabash St
Millersburg, IN 46543
USA

Short VIN/Unit: VG5403602
Model/Item: VGF351G2-81
Dealer: TRI AM RV CENTER OF

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect within **24 hours** after the **secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months** from **delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

Keys	☒ Yes	☐ No
BBQ Grill	☒ Yes	☐ No
Power Cord	☒ Yes	☐ No
Warranty Packet	☒ Yes	☐ No
Sink cover	☒ Yes	☒ No
Jack Handles	☒ Yes	☐ No
TV 1	☒ Yes	☐ No
TV 2	☒ Yes	☐ No
Remotes	☒ Yes	☐ No

(24) Patio door will not latch (25) Rear Ramp door has daylight coming thru
(26) Button on Window Curtain missing

List Any Miscellaneous Comments Regarding Condition of Unit:

- (2) Kitchen Cab rubs when closing/opening
- (3) Bathroom door Edge paint Rubbed off
- (4) Spot on Bottom of Bath. Door
- (5) Top will not lock in place & scratched in 2 places
- (6) Ceiling trim (X2) falling down
- (7) Fascia on Bedroom Slide
- (8) Bedroom door scratched/out of track
- (9) Slide Wall @ Couch has hole
- (10) Brake trim below fireplace
- (16) Wine rack above fridge paint faded

List Any Additional Missing Items:

Suggested areas to inspect: <u>(17) Kitchen BAR Scratched</u> <u>(18) of sink</u>	
Unit Cleanliness	If no, explain: <u>Lots of trash left in compartments</u>
Condition of Flooring	<u>(18) Bubble in lino NAS Storage compartment</u>
Cabinetry Damage	If yes, explain: <u>(13) Hole in WALL Kitchen Under cabinets</u>
Appliance Condition	<u>(11) Kitchen SLIDE AREA Counter scratched.</u> <u>(12) Microwave scratched</u> <u>(14) Stove drawer will not close</u>
Furniture Tears/Stairs	If yes, explain: <u>(17) Hole in wall luan in patio</u> <u>(28) Bathroom Rear door scratches</u>
Frame/Chassis Condition	<u>(29) Trim lock damaged</u> <u>(30) Washer dryer hook up Warp</u>
Roof Components	
Roof Material	
Awning Fabric	
ODS/DS Walls & Graphics	<u>(21) Off door side has alot of puddy sticking out of skirting</u>
Unit Front & Graphics	<u>(22) Front cap damage - per driver</u>
Unit Rear & Graphics	
Additional Notations	<u>(1) Missing Sink cover</u> <u>(15) Fridge door numbers do not light up.</u> <u>(19) Front off door side dent in frame</u> <u>(20) DS around both compartments and front of unit sticky Residu</u> <u>(23) Brake trim beside TV.</u>

Unit/Underside has been washed by the Dealership

Yes

No

Date Washed

Dealer Signature

Stephanie Lewis

Date

6/19/25